

7-18  
5  
21  
81  
85  
75

Bowls 119  
2 123  
129  
Jars 131  
19

55  
41  
119

176  
183  
189  
Hdle 191  
188

166.  
~~200~~  
200  
82

44-137  
79

NG 1032



Factorie

5

971-24

9  
41

82

74-138

74 79



Cologne  
Bottle

Atomizers 97-18

Boxes Page 15

Covers Page 21

Lisc. Page 81

Baskets Page 85

Bottle Cap 95

Creams 99

Bowls 105

Butlers 109

Comports or Bowls 119

Candlestick 123

Salt Mouth 129

Decanting Jars 131

Cylinder 145

Custards 149

Coaster 151

Dish Fern 155

Cone Holder 141

Comports # 119

Cans Molasses

Cologne 153

Bees 157

Carburator Cup 176

Bottles 183

Container Soap 189

Basket Press Hdle 191

Dish 188

Article 179

Sponge Cup

Barrels of M. 166

Bottom Paraf. 196 200

Budda 196-200

Column. Lamp. 82

Decanters 74-137

Chambrane 79



Almonds Footed	194
Articles	181
Book End.	41
Bottoms	37
Aquaria	82
Butter Drainers	109
Cheese and Crackers	34

5

Feet Page 41	
Fish Globe	127
Fork	137
Glasses Bell	148
Flower Block	166 - 168
Glass Cupping	167
Globes	185
Flower Inserts	166
Frame Clock	166
<del>Parrella &amp; On</del>	166
Flyout Traps	167
Exhaust Glasses	167
Graduates	148
Cigarette Holders	141
Goblets	141
Figures or Statues	196 - 161
Flower Pat. Saucers	167
Goshia Girls	196
Match Holders	141
Gay Ball	138



Jars 91-103

Inks 157

Jugs 143

Knobs 93

Jardinere Base. 159

Liners 177

Inserts Flower. 195

Carafe Jug. 143

Lamps 189

Press Stem or Hokey pokey 45

Candle holder 126

Bobshades 96



Mustards 161

Pickles 153

Olives 145

Orals 163

Marmalade 165

Owl. J.M. Page 163

Perulator. J.M. 131

Monkey J.M. 163

Place Card 161

Plates Stuck Up. 62

Platters 67

Nappies Page 51-52-53-54 66

Paper Rack. 41



Trays Page 71  
 Sugars 101  
 Salts 111  
 Syrups 133  
 Spoons 135  
 Tumblers 139  
 Wine Holder 141  
 Stoppers 169 - 173  
 Spoon + Fork 171  
 Salaver 175  
 Stem ware Flat Foot 194 - 178 - 193.  
 Soap Containers 94  
 Sherbet 190  
 Ice Tub. 31  
 Turtle 179  
 Paper Rack 41  
 Swans 110  
 Turkey 110.  
 all glass salt pops page 146



Vaces 115 - 87  
Well ash 74  
adott prism 14







1015 advertising prism m 650-398-318 U.P.W.

2800/235 Pomade Box 37 $\frac{1}{16}$  wide 1 $\frac{1}{8}$  High 4oz weight  
Move 825 moge 383-345-304 U.P.W.

430 Cigarette Box Unfinished  
Move. 750 Presser 398-318 U.P.W.

413 Cigarette Box  
Move. 700 - 398-358-318 U.P.W.

0387 Oval Box J. M. Optic  
Move. 575; 2 Blowers 336 each Gather 269  
Plus cleaning off ways.  
Plain Blower 336 - 2 Gathers 302 each  
Plus 60¢ cleaning off. U.P.W.

0388 Oval Box  
Move. 425; Blower 378 - 2 Gathers 302  
each. Plus 60¢ cleaning off. U.P.W.

0426 Pomade Box J. M.  
Move. 600 Blower 336 Gather 2.68 each  
Plus. 60¢ for cleaning off. When made after  
Optic Rule to govern. All to be warmed in  
U.P.W.

0427 Puff Box J. M.  
Move. 475 Blower 336 Gather 269 each  
Plus. 60¢ each for cleaning off. When made  
Optic. Optic Rule to govern. All to be  
warmed. in U.P.W.

732 12" Hexagon Four Toned Flower Box  
Move 250 Presser 459-449-399 - U.P.W.



616 { Cigarette Box  
 Move. { 625 Presser. 3.98-358-318. U. J. W.

430 { Cigarette Box finished  
 Move. { 700 Presser. 3.98-358-318- U. P. W.

864 { 3 Toed Candy Box  
 Move. { 500 Presser 4.38-3.94-350. U. T. W.

0511 { Oral box  
 move { 475-Blower \$3.78 two gathers  
 \$3.02 Plus 60¢ Each for cleaning off  
 and unlimited turn work

3400 four toed candy box  
 Move Presser 4.48-403-358 U. J. W.

425

1208 Big box  $5\frac{3}{8}$  long  $3\frac{3}{8}$  wide  $1\frac{1}{2}$  in deep

move 550 one mould 600 2 moulds 398-358-318 U. P. W.

3011 Cigarette box move 375-398-358-358-318-4.5-5<sup>U.P.W.</sup>

Mt Vernon 1 lb candy box <sup>m</sup> 400-499-449-448-399 U. P. W.

1312 Cig. Box - 550 - 3.98-3.58-3.18-3.72-3.72-2.53 U. J. W.



0481-0486-0455 Automixer = Machine -  
More. 900 Press 400 - 80% In-TW



2800/235 Pomade Box Cov 3 7/16 wide 1 1/8 High 6 oz weight  
 Move 825 Press 383-345-306 a P W

2630 Pickle Jar Cov Finished  
 Move 825 Press 383-345-306 a P W

1917/415 Tumblers Cover Finished  
 Move 800 Press 398-358-318 a P W

1917/102 Marmalade Cov Unfinished  
 Move 850 Press 345-276 Unlimited Piece Work

104/6 Pull Stem Candy Jar Cov  
 Move 155 Press 344-75 one a P W  
 Two man shop

4070 Sherbet Cover a P W  
 Move 775 Press 358-322-286

4070 Marmalade Cover a P W  
 Move 850 Press 358-322-286

2800/4 Mustard Cover a P W  
 Move 825 Press 358-322-286

4070 5 in Bowl Cover a P W  
 Move 600 Press 379-341-303

2800/4 Mustard Cover a P W  
 Move 825 Press 358-322-286



- 145 Marmalade Cov with Notch u.p.w.  
 Move 850 Press - 358-322-286
- 2800/144 Custard Cov. Move. 825. Presses 358-322-286. a.p.w.  
 1917/96 Sugar Cov u.p.w.  
 Move 725 Press 345-311-276
- 1917/97 Sugar Cov u.p.w.  
 Move 725 Press 345-311-276
- 1917/125 Sugar Cover u.p.w.  
 Move 625 Press 345-311-276
- 1917/124 Sugar Cov u.p.w.  
 Move 625 Press 345-322-276
- 2800/41 Pomade Box Cover  
 Move
- 2970 10in Low Foot Bowl Cover u.p.w.  
 Move 325 Press 449-404-359
- 106 1/2 32g Jug Cover unfinished u.p.w.  
 Move 825 Press 345-276
- 106 1/2 64g Jug Cover unfinished u.p.w.  
 Move 825 Press 345-276
- 071 oblong Box Cover 2 moulds  
 Move 475 wage 358-286- u.p.w.
- 0183 Round Jar Cover 1 mould  
 Move 450 358-286 u.p.w.  
 Close Selection

- 2970 Straw Jar Cover  
 Move
- 0115 Square Butter Cover.  
 Move
- 676 Round Jar Cover w 5in H. 2 in top Knot  
 Move 475 - 345-276 - u.p.w.
- 1152 Mustard Cover unfinished  
 Move 925 Press 345-276
- 2811 Puff Box Cover Large  
 Move
- 0243 Desiccator Cover  
 Move
- 0135 Desiccator Cover  
 Move
- 2800/79 Puff Box Cover  
 Move 775 - Press 383-345-306 a.p.w.  
 If mold is O.K.
- 2795 Puff Box Cover  
 Move 475 - 383-345-306. a.p.w.  
 If mould is O.K.
- 2722 5in Nappie Cover with hole  
 Move
- No 2 Armor Jar Cov 2 moulds  
 Move 550 - 358-286 u.p.w.



107 Jug Cov. unfinished  
 Move 700 345-276 W.P.W.

12 in Barrell Cover W.P.W.  
 Move 225 wage 449-449-359

14 in Barrell Cov W.P.W.  
 Move 175 Wage 449-449-359

18 in Barrell Cov  
 Move

Straw Mustard Cov  
 Move 850 383-345-306 Q.P.W.

Large Kitchen Jar Cov one mould  
 Move 425 358-286 Q.P.W.

0238 Manicure Cov oval covers 6x5.  
 Move 600 358-286 W.P.W.

2245 9 Cov Pull Stem  
 Move 95 wage 366-366-75% W.T.W.

Bosworth Jar Cov  
 Move 1080 wage 345-276 W.P.W.  
 Close Selections

91 Jug Covers  
 Move 825 345-276 W.P.W.

2800/234 Soap Dish Cov  
 Move 765 345-341-276 W.P.W.

2991 Puff Boy Cov  
 Move 775 Passer 383-345-306 Q.P.W.

~~Strat No 74 Mustard Cov~~  
 Move

107 1/2 22g Sugar Cover  
 Move 850 383-306 Q.P.W.

144 Cover  
 Move 950 383-306 W.P.W.

Pull Stem Covers when made out of dense colors  
 10% less in moves

105 Candy Jar Cover Pull Stem  
 Move 230 423-75% W.T.W.

104 6 1/2 in Cover Pull Stem  
 Move 145 423-75% W.T.W.

104 7 in Cover Pull Stem  
 Move 130 423-75% W.T.W.

104 8 in Cover Pull Stem  
 Move 115 423-75% W.T.W.

47 Jug Cov. Pull Stem  
 Move 230 B. 423 & 75% Q.T.W.  
 10% reduction in moves when made out of dense colors.

501-5" Cover. Move. 625-383-345-306.  
 Q.P.W.

502. 6" Cover Move 600-438-394-350.  
 Q.P.W.

351-7" Oval Cov. Move 600-438-394-350.  
 Q.P.W.



2800-242 Sugar Cover

Move. 775 Presser 383 7. 345-9306. Q.P.W.

2800/149 Bottle Cover

Move. 600 Presser 398-388-318 Q.P.W.

510 Rose Jar Cover Unfinished

Move. 750 Presser 383-306 Q.P.W.

2748 Agar Jar Cover

Move 355 Presser 398-318 Q.P.W.

601 Candy Jar Cover Unfinished

Move 850 Presser 383-306 Q.P.W.

430 Cigarette Box Cover Unfinished

Move 950 Presser 383-306 Q.P.W.

582 Puff Box Cover

Move. 825 Presser 383-345-306. Q.P.W.

3075 Jug Cover. Unf.

Move. 700 Presser 383-306 Q.P.W.

123 Jug Cover. Unf.

Move. 700 Press-383-306 Q.P.W.

4071-83 Cover Unf.

Move. 950 Presser 383-306 Q.P.W.

413 Cigarette Box Cover

Move. 700 - 383-345-306 Q.P.W.

If mold is in working order.

680 9" Vanity Cover.

Move. 425; Presser. 438-394-350. Q.P.W.

2590 Lemon Dish Cover. Unfinished

Move. 685. Presser 383-306. Q.P.W.

579 4" Cover Paste Mould. with Knob.

Move. 475 Blower 381 Gather 80%. Q.T.W.

0408 Jar Cover

Move. 650 Presser 383-306 Q.P.W.

395 Butter Tub Cover

Move. 625 Presser 398-388-318 - Q.P.W.

688 Cover. P. Mould.

Move. 200 Blower 423 Gather 75% Q.T.W.

0468 Cover Paste Mould.

Move. 550 Blower 60F per Hundred Gather 80% Q.P.W.

3075 Honey Dish Cover

Move. 290 Blower 3.81-Gather 80% Q.P.W.

3075/10 Jug Cover Plain

Move. 290 Blower 4.23 Gather 75% Q.T.W.  
10% less for optic

950 12" Oval Cover

Move. 200 Presser. 4.99-4.49-3.99. Q.T.W.

885 Cigarette Jar. Cover.

Move. 850 Presser. 3.83-345-306. Q.P.W.



- 764 $\frac{1}{2}$  4" Cover.  
More. 600 Presser. 3.98-318. U. P. W.
- 764 $\frac{1}{2}$  5" Cover.  
More. 500 Presser. 3.98-3.18. U. P. W.
- 764 $\frac{1}{2}$  6" Cover.  
More. 450 Presser. 4.38-350. U. P. W.
- 507 4 $\frac{1}{2}$ " Cover  
More. 675 Presser. 3.83-345-306. U. T. W.
- 864 4 $\frac{1}{2}$ " Cover.  
More. 675 Presser. 3.83-345-306. U. P. W.
- 951 Toast Dish Cover.  
More. 500 Presser. 4.38-3.94-3.50. U. T. W.
- 802 Cover  
More. 850 Presser. 3.83-306 U. P. W.
- 803 Cover  
More. 675 Presser. 3.98-318 U. P. W.
- 838 Mustard Cover  
More. 925 Presser 3.83-306. U. P. W.
- 688 6" Pull Knot Cover  
More. 200 Plain 180 Optics Blower. 4.23-70 $\frac{1}{2}$  U. T. W.
- 683 Cover Large  
More. 775 Presser 3.83-3.48-3.06. U. P. W.

- 683 Cover Small  
More. 900 Presser. 3.83-345-306. U. P. W.
- 912 7" Cover  
More. 475 Presser. 4.38-3.94-350. U. P. W.
- 605-615 Cigarette Box Cover  
More. 700 Presser. 3.98-358-318. U. T. W.
- 616 Cigarette Bot Cover  
More. 650 Presser. 3.98-3.58-3.18. U. T. W.
- 3400 4 $\frac{5}{8}$  in. Butter cover  
More Presser 3.98 3.58-318 U. P. W.  
675
- 3400 5 in. Candy box cover  
More  
625 Presser 3.83, 345 3.06 U. P. W.  
430 Cig box cov leng 3 $\frac{5}{8}$  width 2 $\frac{5}{8}$ <sup>more</sup> 850 3.83-345-306 U. P. W.  
120 Cig box cover work to tool cover list  
3 inch bandage jar cov. more 700-383-306-U. P. W.  
Turkey cover more 450-398-318-U. P. W.  
882 Tobacco jar cov screw thread 700-383-306 U. P. W.  
834 or 838 mustard cov 925-383-306-U. P. W.
- No. 29 Mt. Vernon Mustard Cov. 750-383-345-306-U. P. W.



110 Ice Tub. P. M.

Move. 200 Blower 455-455-364 U. T. W.

395 Butty Tub

Move. 575 Presser 398-358-318 U. P. W.

968 Sherbet Pull Stem

Move. 335 Plain 305 Optic Blower. 387-381

75% U. J. W.







3400 Cheese and crackers  
7

More 600 3.98-3.58-3.23-3.18 W.J.W.



685 Bottom  
More. 450 Blows. 3.81 - 75% U. T. W.

686. Bottom  
More. 350 Blows. 3.81 - 75% U. T. W.

687 Bottom  
More. 250 Blows. 3.81 - 75% U. T. W.







405 Lamp Foot Fin

2677 Wace Foot Fin  
made 573 lost 16.

J.H.F.

2750 12 in Punch Bowl Foot  
move  
made 573 lost 16

J.H.F.

2718 Lamp Foot  
move

17 1/2 in Punch Bowl Foot  
2804/28 Punch Bowl Foot  
move

511 Book End.

move. 250 Presser 4.99 - Githu 3.99. Q. T.W.

710 Paper Rack

move. 250 Presser. 4.48-409-358. Q. T.W.



0402 Bottle P. M.  
 Move. 275 Blower 455-455-364 U. T. W.

0435 Bottle P. M.  
 Move. 280 Optic - 300 Plain, Paste Mould  
 Wags. U. T. W.

831 Oil Bottle J. M.  
 Move. 600 Blower 3.78 Gather 362 each  
 Out. Finisher 3.95 U. P. W.

0430 Cologne Bottle J. M.  
 Move. 750 Blower 3.78 Finisher 3.95  
 Gather 3.62 each Out. U. P. W.

619 Oil Bottle J. M.  
 Move. 600 Blower 3.78 Finisher 3.95  
 Gather 362 each Out. U. P. W.

1170 40 g. Pinch Bottle J. M.  
 Move. 350 Blower 3.78 Finisher 3.95 Gather 302  
 each Plus 60¢ each for cleaning off  
 U. P. W.



3140 10 oz Ftd tumbler <sup>move 2792-9</sup> 450-423-423-318  
 3140 Low Ftd sherbit 475-423-423-318  
 3140 12 oz Ftd tumbler 425-423-423-318  
 3115 Cordial 525-423-423-318  
 3120 Cordial 525-423-423-318  
 10% over for a move good.

3130 Line Prestem  
 " Goblet. Move 450  
 " Champaign " 450  
 " Sherbit " 475  
 " Cock Tail " 490  
 " Cordial " 525  
 10% over for a move good  
 wages 423-423-318 2.70

3135 Line Press stem  
 " Gob Move 450  
 " Champ " 450  
 " Sherbit 475  
 " Cock Tail 490  
 " Cordial 525  
 10% over for a move good  
 wages 423-423-318-270

3135 Wine. Move 490. 423-423  
 3.17-2.70. U.T.W.  
 10% Bonus per move good.

3140 Hot Whiskey. Move 500. - 4.23.  
 4.23-3.17 2.70. U.T.W.  
 10% Bonus per move good.











2800/151 8 in Nappie Shallow.

Move

235 6 in Deep Nappie

Move 475 wage 398-358-318 w.P.W.

3100 6 in Nappie 1924

Move 625 438-394-350 w.P.W.

3100 7 in Nappie 1924

Move 500 wage 481-433-385 w.P.W.

3100 7 in Deep Nappie

3 Move 375 499-449-399 w.P.W.

3100 8 in Nappie Deep

Move 325 w.L turn work  
Wage. 449-404-359

made 342 loss 9

0130

073 odd Shape Nappie  $5\frac{3}{8}$  long  $3\frac{3}{8}$  wide

$1\frac{1}{2}$  High 6g weight unfinished

Move set. Dec 9/1922 Move 750 Presses 358

Gather 286 unlimited Piece work R.J.M.

1917/131 5 in one Handle Nappie Joint mould  
Snapped.

2590  $3\frac{1}{2}$  in Nappie 1924

Move 1025 383-345-306 w.P.W.

2925 6 in Partition Nappie hole in Leister

Move 425 Press 394-355-315. U.T.W.



035 4 1/2 Nappie move 675 Press 358-286  
unlimited Piece work unfinished

0120 6in Nappie 3 Partition move 475 Press 394-315  
unlimited Turn work unfinished

0119 5in Nappie 3 Partition move 550 Press 394-315  
unlimited Turn work unfinished

134-8in Nappie to Plate 10 1/2 in with seat  
move 425 Press 433-409-346  
unlimited Turn work finished

2800/234 oval Nappie with seat for soap  
move 690 383-345-306

4070/49 4 1/2 in Nappie Block mould  
move 850 <sup>in</sup> ~~dispute~~ 345-311-276 u.P.W.

4070/50 4in Nappie Block mould  
move 900 <sup>in</sup> ~~dispute~~ 345-311-276 u.P.W.

1917/332 6in Nappie to Plate  
move 560 - 438-394-350 u.T.W.

1917/101 4" Nap. ~~Plate~~ Plate  
move 725 Press 422-394-333  
2960 6in 2 Handle Nappie

2590 Liner Nappie unfinished  
move 775 Press 358-286 u.L.P. work

0106 6in Nappie straight sided  
move 500 - 438-394-350 u.P.W.  
made ~~419~~ <sup>475</sup> 550. unfinished.

No 6 6in Nappie to Basket  
move

made 550 loss 189

gas m

112 Square Nappie  
move

1917/266 4in Nappie u.P.W.  
move 825 Press 345-311-276

073 odd Shape Nappie finished

1917/178 - 6in Nappie Three Tocs  
move 625 Press 383-345-306

2800/234 12 in Shallow Nappie  
move 185 Press 499-449-499 u.T.W.

Strathford 8in Nappie Spike Edge  
move 350 Press 449-404-359



Strathford 8 in Nappie Plain Edge <sup>1923</sup>  
 Move 400 Press 394-355-315 uPW  
 agreed to take small Blesies

Strathford 9 in <sup>1923</sup> Nappie Spike Edge  
 Move 300 Press 449-404-359

Strathford 9 in <sup>1923</sup> Nappie Plain Edge  
 Move 300 Press 449-404-359

2699 11 in Nappie 1923 uPW  
 Move 150 Press 449-404-359

4070 5 in toed Nappie 1923 uPW  
 Move 525 Press 394-355-315

4070 8 in Nappie Stuck up <sup>1923</sup> uPW  
 Move 385 Press 433-390-346

4070 7 Nappie Stuck up 1923 uPW  
 Move 500 Press 433-390-346

4070 5 in Baked Apple toed 1923 uPW  
 Move 500 Press 394-394-315

2590 1/2 3 1/2 in new Star Bottom <sup>1923</sup> uPW  
 Move 725 Press 358-322-286

2590 1/2 3 1/2 in new Star Bottom Deep <sup>1923</sup> uPW  
 Move 725 Press 358-322-286

2882 4 7/8 in Nappie unfinished uPW  
 Move 825 Press 345-276 1923

1917/148 4 in Nappie to Plate <sup>1923</sup> uPW  
 Move 775 Press 380-355-304

2852 5 in Handli Nappie 1923 uPW  
 Move 625 Press 345-311-276

153 4 1/2 in Cylinder Ring Nappie <sup>1923</sup> uPW  
 Move 775 Press 345-311-276

0104 5 in Nappie 1923 uPW  
 Move 575 Press 358-322-286

2590 1/2 9 in Nappie  
 Move

2800/152 5 in 3 toed Nappie  
 Move

4070 6 in Nappie  
 Move

4070 6 in Nappie Deep Ring  
 Move

2199 3 1/2 in Nappie  
 Move

2852 3 1/2 in Nappie  
 Move

2852 4 in Nappie  
 Move



- 2850 3½ in Nappie  
Move
- 0120 8 in Partition Nappie  
Move
- 4070 8 Nappie Snapped up Shallow Ring 1923  
Move 400 394-355-315 u.P.W.
- 4070/187 5 in Hdl Nappie  
Move
- 2699 8 in Square Nappie 1923  
Move 275 - 449-404-359 u.P.W.
- 2943 10 in Nappie  
Move 250. Press. 499-449-399. u.P.W.
- 2943 12 in Nappie  
Move 215 - Press. 499-449-399. u.P.W.
- 2943 7 in Nappie Flat Bottom 1923  
Move 450 394-355-315 u.P.W.
- 4022 8 in Nappie 3 Loes u.P.W.  
Move 225 loose 5 apr  
Head Shop Blank Wage
- No 20 5 in Nappie 1924  
Move 690 383-345-306 u.P.W.
- 8.2 4 in Nappie  
Move
- 0212 oval Nappie 1923  
Move 650 Wage 358-286 u.P.W.

- 0195 7 in Oval Nappie unfinished 1923  
Move 500 358-286 u.P.W.
- 0211 4½ in Nappie  
Move
- 37 6 in Deep Nappie  
Move
- 0120 8 Nappie Partition 3004 1924  
Move 360 499-449-399 u.P.W.
- 148 7 in Nappie to Plate 1924  
Move 450 Wage 481-453-384 u.P.W.
- 149 7 in Nappie to Plate 1924  
Move 450 Wage 481-453-362 u.P.W.
- Str 4½ in Nappie Plain Edge  
Move
- Str 4½ in Nappie Scallops Edge  
Move
- 015 odd Shape Nappie  
Move
- 2590 4 in Oval Nappie unfinished  
Move 950 383-306 u.P.W.
- 312 8 in Block Mould Nappie 1924  
Move 425 481-433-386 u.P.W.
- 2800 of 234-6" Nappy with seat.  
Move 550 398-358-318. u.P.W.



0120 7in Nappie 3004 Partition 1924  
Move 425 499-449-399 U.T.W.

Strap 8in Sheep Nappie Plain Ring  
Move 325-499-449-399 Q.P.W.

233<sup>1/4</sup> Oval Nappie to Plate

Move 625-2.7W-438-434-350

243 and 244 9in Nappie to Plate

Move 325 538-483-430 U.T.W.

4050 7in Sheep Nappie or Comfort

Move 400 499-449-399 U.P.W.

Strath 8in two Handle Nappie

Move 375 438-394-350 U.P.W.

Agreed to work 2 or 4 Compartment Nappie  
Same as 3 Compartment.

468-5<sup>1/4</sup>-Nappie to Plate 394

Move 625. Q. J.W. 438-~~434~~-350.

232. Oval Nappie

Move. 625.- Press. 438-394-350 Q.P.W.

478.- Oval Plate

Move. 525- Press. 438-434-350. Q.J.W.

334-7"-3 Partition 2 Ald. Nappie

Move. 380-Press. 499-449-399 Q. J.W.

336-7" 4- Partition 2 Ald Nappie

Move. 380- Press. 499-449-399. Q. J.W.

338-8" 3 Partition 2 Ald. Nappie.

Move. 340- Press. 499-449-399. Q. J.W.

340-8" 4 Partition 2 Ald. Nappie

Move. 340 Press. 499-449-399. Q. J.W.

474 6" Nappie to Plate

Move. 560- Press 438-434-350. Q. J.W.

2590 3<sup>1/2</sup>" Nappie

Move. 1025- 383-345-306 Q.P.W.

0342-4" Nappie 3 Moulds

Move. 775 398-~~398~~-318.

0317. Oval Nappie 2 Part

Move 450. Presser 438 7. 394-9. 350 Q. P.W.

0120<sup>1/2</sup> Partition Nappie

Move 425- Presser 438- 7. 394 9. 350 Q. J.W.

481 4" Nappie to Plate

Move. 725, Presser 422-394-337 Q. J.W.

581 4" Froth Nappie

Move 750 Presser 398-358-318 Q.P.W.

466 Nappie or Baked Apple.

Move 600 Presser 398-398-318 U.P.W.

~~486-487 10" Oval to 12" Plate~~

~~Move 400 Presser 480-454-384 Q. T.W.~~

2975 6" 1 Part Square Nappie

Move 400 Presser 438-394-350. Q. J.W.

381 6" Deep Nappie

Move. 500 Press 398-358-318. Finishes 25 Feet  
for rolled edge. 10% added when a mat is selected  
good. Q.P.W.



594-595-596-694-695-696  
6 in Napfny to Plate  
Move. 600 Presser 383-385-306 U.P.W.  
10% added to wages when a move is selected per  
Snapped. up. plates

4072 8" Deep Napfny  
Move. 325 Presser 499-449-399 U.P.W.

4071 4" Napfny  
Move. 850 Presser 383-345-306. U.P.W.

0104 5" Napfny Unfinished  
Move. 675 Presser 398-318 U.P.W.

486-487-12 in Oval Plate  
Move. 275 Presser 499-499-399. U.P.W.

0451 5" Flanged Napfny  
Move. 800 Presser. 398-318. U.P.W.

0452 6" Flanged Napfny  
Move. 750 Presser. 398-318. U.P.W.

0317 8" Two Part Napfny Unfinished  
Move. 500 Presser 438-350. U.P.W.

699 11" Deep Napfny  
Move. 200 Presser. 499-449-399. U.T.W.

672 9" Deep Napfny  
Move. 265 Presser 499-449-399. U.T.W.

#14 7" Deep Napfny  
Move. 380. Presser 499-449-399. U.T.W.

#931 5" Square Napfny  
Move. 725 Presser 398-358-318. U.T.W.

#932 10" Square Napfny  
Move. 325 Presser 499-449-399. U.T.W.

759 5" 2 Hld. Plate  
Move. 570 Presser. 398-385-318. U.T.W.

749 5" 2 Hld. Taper Shape Napfny  
Move. 689 Presser. 383-345-306. U.T.W.

760 5" 2 Hld. Napfny Basket Shape  
Move. 570-Presser 398-385-318. U.T.W.

758 5" 2 Hld. Napfny Mould Shape  
Move. 689. Presser. 383-345-306. U.T.W.

0378 Grill Plate  
Move. 290 Presser. 499-449-399. U.T.W.

912 Napfny  
Move. 350 Presser. 499-449-399. U.T.W.

300/1917/287- 7" 3 Toed Napfny  
Move. 450 Presser. 438-394-350. U.T.W.  
25¢ extra for finisher

806 Napfny. Flat Rim  
Move. 775 Presser. 398-358-318.  
25¢ extra for finisher



## Stuck up Plates.

Sizes	Round Plates	Q.T.W.
4"	More. 800 Presser. 3.95-370-315	
4 1/2	" 775 " 3.95-370-315	
5	" 725 " 3.95-370-315	
6	" 675 " 3.95-3.85-315	
7	" 600 " 3.95-3.85-315	
8	" 550 " 4.38-4.09-350	
9	" 4.75 " 4.45-4.19-358	
10	" 4.00 " 4.99-4.49-3.99	
11	" 350 " 4.99-4.49-3.99	
12	" 260 " 4.99-4.99-3.99	
13	" 225 " 4.99-4.99-3.99	
14	" 190 " 4.99-4.99-3.99	
15	" 150 " 4.99-4.49-3.99	

All Stuck up Plates worked Q.T.W.  
Measured after finished.

Sizes	Oral Plates Stuck Up.	Q.T.W.
6	More. <del>1.75</del> 6.75 Presser. 3.95-3.85-315	
7	" 6.25 " 3.95-3.85-315	
8	" 5.75 " 4.38-4.09-350	
9	" 5.00 " 4.48-4.19-3.58	
10	" 4.25 " 4.99-4.49-3.99	
11	" 350 " 4.99-4.49-3.99	
12	" 275 " 4.99-4.99-3.99	
13	" 240 " 4.99-4.99-3.99	
14	" 200 " 4.99-4.99-3.99	
15	" 165 " 4.99-4.99-3.99	

Measured after finished Q.T.W.

299/ 1917/168 - 6" 3'ood Napfy.  
More. 600 Presser. 3.83-345-306. Q.T.W.  
25¢ extra for finishes

922 5" Ald. Napfy 2 handles.  
More. 730 Presser. 3.99-358-3.18. Q.T.W.

911 Napfy. or Dish  
More. 350 Presser. 4.99-4.49-3.99. Q.T.W.

1085 7" Napfy  
More. 450 Presser. 4.38-394-350. Q.P.W.

1086 8" Deep Napfy.  
More. 332 Presser. 4.99-4.49-3.99. Q.P.W.

745 5" Deep Napfy  
More. 350 Presser. 4.99-4.49-3.99. Q.T.W.  
Hever Boy to be furnished.

958-959 Relish Dish-Partition  
More. 325 Presser. 4.99-4.49-3.99. Q.T.W.

697-698- Plate 8 inch  
More. 600 Presser 3.83-385-306. Q.T.W.

692 Plate 6 inch  
More. 700 Presser. 3.83-370-3.06. Q.T.W.

1200 Grill Plate  
More 325 Presser 4.48 Finished 4.03  
Satherer 358 Q.T.W.



380 Grill Plate  
 move 325 Presser \$4.48 Finisher \$4.03  
 Gather \$3.58 U.T.W.

3400 Grill Plate  
 move 325-Presser \$4.48 Finisher \$4.03  
 Gather \$3.58 U.T.W.

3400 11 in. Plate with two lugs  
 or handles.  
 Move 350-Presser 4.99-4.49-3.99  
 Pending adjustment by  
 conference. U.T.W.

3400 7 in. Plate with two lugs  
 or handles.  
 Move 600 Presser 3.98-3.58-3.18 U.T.W.  
 Pending adjustment by  
 conference.

7222 10 in plate worked to stick up plate agreement  
 3400/22 10 " " " " " " " " " "  
 3400/83 4 5/8 in " " " " " " " " "  
 3400/85 6 3/8 " " " " " " " " "  
 3400/75 7 3/8 " " " " " " " agreement

Mt. Vernon ~~1494-15 napery~~  
 4 in. ~~7 1/2 in. plate~~ to 18 in. plate 125  
 4.99 - 4.99 - 3.99 - U.T.W.







(Warmed in on former)

906 16" Platter  
 Move. 125 Press. 4.99-4.49-4.99 U.T.W.

904 14" Platter  
 Move. 175 Press. 4.99-4.49-3.99 U.T.W.

905 15" Platter  
 Move. 140 Press. 4.99-4.49-3.99 U.T.W.

903 13" Platter  
 Move. 200 Press. 4.99-4.49-3.99 U.T.W.

902 12" Platter  
 Move. 225 Press. 4.99-4.49-3.99 U.T.W.

901 11" Platter  
 Move. 290 Press. 4.99-4.49-3.99 U.T.W.

900 10" Platter  
 Move. 300 Press. 4.99-4.49-3.99 U.T.W.

899 9" Platter  
 Move. 425 Press. 4.48-4.03-3.58 U.T.W.

1077 10" Oval Platter  
 Move. 425 Press. 4.99-4.49-3.99 U.T.W.  
 10% added when move is selected good on all salable ware.

1078 12" Oval Platter  
 Move. 275 Press. 4.99-4.99-3.99 U.T.W.  
 10% added when a move is selected good on all salable ware

1079 15" Oval Platter  
 Move. 165 Press. 4.99-4.99-3.99 U.T.W.  
 10% added when a move is selected good on all salable ware.

3400 11½ inch Platter  
 move 250 4.99-4.99-3.99 U.T.W.

{ 3400/57 11 in Platter, move 3.30  
 3400/58 13 " " " " 2.25 }  
 Head shop wages U.T.W.



2651. Tray  $7\frac{5}{16}$  long  $\frac{3}{4}$  high 17oz weight  
 unfinished 1 mould  
 move set Dec 9 1922 move 525 Presser 358  
 Gather 286 Unlimited Piece Work R.J.M.

2800/22 Tooth Pick Tray  $3\frac{1}{2}$  long  $1\frac{1}{16}$  wide  $\frac{1}{2}$  high  
 weight 4g Finished move set Dec 9 1922  
 move 700 Presser 345 Fin 311 Gath 272 wLPW  
 unlimited Piece Work C.M.

0295 Ash Tray 1923 unfinished wPW  
 move 410 wage 358 - 286 wPW

2800/235 Tray 1924  
 move 325 499-449-399 wPW

217 oval Tray Ash  
 move 850 383-345-306 wPW

2034 10in Tray one mould

made 233 loss 28

D.B.C

move

move



- No 3 Developing Tray  $6\frac{1}{4} \times 5\frac{1}{4}$   
 Move 650 Wage 358-322-286 U.P.W.
- No 3 1/2 Developing Tray  $7\frac{1}{4} \times 5\frac{3}{4}$   
 Move 600 Wage 358-322-286 U.P.W.
- No 4 Developing Tray  $9\frac{3}{4} \times 6\frac{7}{8}$   
 Move 450 Wage 358-322-286 U.P.W.
- No 5 Developing Tray  $10\frac{1}{2} \times 8\frac{5}{16}$   
 Move 425 Wage 394-355-315 U.P.W.
- No 6 Developing Tray  $11\frac{3}{4} \times 9\frac{23}{32}$   
 Move 325 Wage 449-404-359 U.T.W.
- No 112 Square Tray  
 Move 850 383-345-306 U.P.W.
- 2800/235 Ring Tray  
 Move 725 438-438-350 U.T.W.
- No 177 5in Tray  
 Move
- 4070/87 2 Hole Spoon Tray  
 Move
- 1917/50 12in Celery Tray 1924  
 Move 375 492-443-393 U.P.W.
- 4070/102 12in Celery Tray 1924  
 Move 375 492-443-393 U.P.W.

- 209 Tray 1924 10in  
 Move 250 499-449-399 U.T.W.
488. Tray Presser 448-7. 403 G. 358.  
 Move 400 ~~Presser 458-7. 394 G. 358 & P.W.~~
- 389 - 6 Compartment Tray 13 inch  
 Move 200. Presser 499-449-399 U.T.W.
- 326 Ald Relish Tray  
 Move 225 Presser 499-499-399 U.T.W.
- 387 2 1/2 in. Ash Tray  
 Move 850 Presser 398-358-318 U.P.W.
- 0315 8" Ash Tray  
 Move 250 Presser 499-449-399 U.P.W.
- 2991 10" Oval Tray  
 Move 325 Presser 448-403-358 U.P.W.
- 621 Tray Serving  
 Move 425 Presser 449-449-399 U.T.W.
- 623 Serving Tray  
 Move 375 Presser 499-449-399 U.T.W.
- 660 11" Vanity Tray  
 Move 290 Presser 448-403-358 U.P.W.
- 386 Relish Tray 3 part 10 1/4 in  
 Move 350 Presser 499-449-399 U.T.W.



0376 Ash Well  
Move. 550 Press 398-358-318 Q.P.W.

3075/2 Ald. Decanter Paste Mold.  
Move. 175 Blower 455-455 - Shear 485  
Sawdler 485 Gather 364 Q.T.W. 283.

3075/1 Decanter No Ald.  
Move. 200 Blower 455-455 - Shear  
485 Gather 364 Q.T.W. 283.

4071 Champagne  
Move. 725 Press 398-358-323-318  
Q.P.W. Straitening Bay furnished.

3075/4 Decanter Paste Mold. No Ald.  
Move. 175. Blower 455 Finisher 485  
Foot Paster 455 Gather 364. Q.T.W.

3075/3 Decanter Ald & Ald. Paste Mold  
Move. 150 - Blower 455 Finisher 485  
Sawdler 485 Foot Paster 455 Gather 364. Q.T.W.

641 Ash Well J. M. Optic  
Move. 525 Blower 378 Gather 362 each  
net. Optic rule to govern

643 Ash Well J. M. Optic  
Move. 400 Blower 404 Gather 362 each  
net. Optic Rule to Govern

644 Ash Well  
Move. 325 Blower 404 Gather 362 each net  
Optic Rule to Govern.

680 Vanity Tray Bottom  
Move. 425 Press 438-350 Q.T.W.

492 Tray 10 7/16 diam  
Move. 325 Press 499-449-399 Q.P.W.

392 Tray Partition Diam 10 7/16  
Move. 300 Press. 499-449-399. Q.T.W.

2370 Ind. Ash Tray  
Move. 950 Press. 383-315 Q.P.W.

820 Ald. Service Tray.  
Move. 450. Press. 499-449-399. Q.T.W.

830 Condiment Tray Ald.  
Move. 400 Press. 499-449-399. Q.T.W.

397 Relish Tray  
Move. 250 Press. 499-449-399. Q.T.W.

488 Tray Unfinished  
Move. 450 Press 4.48-358 Q.P.W.

837 Ald. Tray  
Move. 600 Press. 4.38-3.94-350 Q.T.W.

829 Ald. Tray  
Move. 350 Press 4.99-4.49-399. Q.T.W.

390 6" Ash Tray  
Move. 425 Press 4.38-3.94-3.50. Q.P.W.



- 908 *leekery Tray*  
 Move. 4.25 Presser. 4.48-4.03-3.58. U.T.W.
- 641 *Ash Well Top*  
 Move. 650 Presser. 3.98-3.58-3.18. U.P.W.
- 1095 *Sugar-Cream Tray*  
 Move. 4.25 Presser. 4.99-4.49-3.99. U.T.W.
- 880 *Bridge Tray*  
 Move. 3.75 Presser. 4.99-4.49-3.99. U.T.W.
- 1083 *Tray*  
 Move. 4.25 Presser. 4.48-4.03-3.58. U.T.W.
- 1068 *Tray Partition*  
 Move. 3.75 Presser. 4.48-4.03-3.58. U.T.W.
- 973 *Tray*  
 Move. 650 Presser. 3.98-3.18. U.T.W.
- 642 *Ash Well. Machine*  
 Move. 625 Presser. 4.00-90%<sup>20</sup>-80%. U.T.W.
- 1031 *13" Cake Plate Tray.*  
 Move. 1.90 Presser 4.99-4.49-3.99. U.T.W.
- 898 *Asparagus Tray*  
 Move. 2.00 Presser 4.99-4.49-3.99 U.T.W.

- 861 <sup>Handle</sup> *Relish Tray 11 inches dia.*  
 move 2.25. wages Presser 4.99  
 Finisher 4.99 Gather 3.99 U.T.W.
- 1159 *Relish Tray or platter with  
 partition move 1.40 wages  
 presser 4.99-Finisher 4.49  
 Gather 3.99 U.T.W.*
- 1160 *Relish Tray or platter  
 without partition move 1.50  
 wages Presser 4.99 Finisher  
 4.49 Gather 3.99 U.T.W.*
- 862 *Tray*  
 move 3.75-4.99-4.49-3.99 U.T.W.
- 1093 *Relish Tray*  
 move 4.25. 4.99-4.49-3.99 U.P.W.
- 3400 *Selry or Relish Tray*  
 move 2.50-4.99-4.49-3.99 U.T.W.
- 3400 *Sandwich Tray Handled.*  
 move 3.00-4.99-4.99-3.99 U.T.W.
- 3400/90 *6½ in 2 compartment 2 hld relish tray*  
 move 4.25. 4.98-3.94-3.50 U.T.W.
- 3400/91 *7½ in 3 compartment 3 hld relish tray*  
 move 3.80-4.99-4.49-3.99 U.T.W.
- 1094 *16 in 2 hld oval tray move 1.25*  
 4.99-4.49-3.99 U.T.W.
- 1215-2 hld tray <sup>m</sup> 7.75-3.95-3.18 U.P.W.



- 1179 oblong tray <sup>m</sup> 335-4.48-3.58 U.P.W.
- 3400/88 Pelish tray 2 part 2 hld 1 mold,  
more 5.35 3.98-3.58-3.18 U.J.W.
- 3011 ash Tray more <sup>m</sup> 375-398-358-358-318-455 U.P.W.
- 617 ash tray 3 inch <sup>lower more</sup> or tray 1000-383-306 U.P.W.
- 2369 " " 3 1/2 " " 1000-383-306 U.P.W.
- 652 11 inch Celery tray <sup>m</sup> 425-4.48-4.03-3.58 U.P.W.
- 3400/87 " " " 2 hld " <sup>m</sup> 390-4.48-4.03-3.58 U.P.W.
- 3400/89 " " 2 hld with compartment <sup>m</sup> 390-4.48-4.03-3.58 U.P.W.
- 1313 Ash Tray 350-4.28-3.94-3.50-~~3~~-4.55-3.58 U.J.W.
- 1314-1066 " " 500-3.98-3.58-4.23-2.70-3.18 U.J.W.
- 1311 Ash Tray 500-3.98-3.58-3.18-3.72-3.72-2.53-4.7 U.

- 3145 Decanter. More <sup>blower</sup> 350-4.16  
fin. 3.95 Two gath. 3.02 plus  
60 cents. for cleaning off.  
U.J.W.



0256 6 in Disc 4 to 6 holes  
 Move 375 approx 394-355-315 on P.W.

0243 Disc  
 Move 375 Presser 438-394-350 on P.W.  
~~made 390 holes~~ E.P.W.



0359 Lamp Column P. M.  
 Move. 250 Blower 455-364 U. T. W.

565 1/2 Lamp Column 18 qt  
 Move. Crystal 400 Solid Colors 350  
 Blower 336 Gather 269 each Plus 60¢  
 Clearing off.

566 1/2 Lamp Column 26 qt  
 Move. Crystal 325 Solid Colors 250  
 Blower 378 Gather 302 each Plus 60¢

568 1/2 Lamp Column 26 qt  
 Move. 325 Crystal - 250 Solid Colors  
 Blower 378 - Gather 302 each Plus 60¢

1002 Drum Shape Aquaria  
 Move. 120 Blower 462 Gather 3.70 each  
 plus 60¢ each for cleaning off. No 5% loss. U. T. W.



No 6 6 in Nappie Basket.

082 Oval Basket

More. 500 Presser 398-398-318. Q.P.W.

Without Handle. More. 5-25 same size

1182 2 hlt basket 570-398-358-318 Q.P.W.



569 1/2 Vase J. Am. 56 g wt  
 Move. 120 Blower 420-2 gather 396 each  
 net.

2366 8" Vase Pull Stem  
 Move. out of Jade Green 10% less than  
 regular move.

0379 Vase Pull Stem No foot  
 Move. 370 Blower 381-75% 2 man shop

2374 13" Vase Pull Stem.  
 Move. 95 Plain or Optic Blower 455-455-  
 364 In TW.

2374 11" Vase Pull Stem  
 Move. 140 Plain or Optic Blower 455-455-  
 364. In TW.

2374 7" Vase Pull Stem.  
 Move. 285 Optic only Blower 423-423 70%  
 In TW.

2374 6" Vase Pull Stem  
 Move 335 Optic only Blower 423-423  
 75% In TW.

Vases 2 man shop Paste mould.

301-6"	6 1/2	g.	Move. 370	Blower.	455-364.	In TW
302-"	7 1/2	"	"	370	"	455-364 " " "
303-6 1/4	6 1/2	"	"	370	"	455-364 " " "
304-5 7/8	9	"	"	370	"	455-364 " " "
305-6"	13 1/2	"	"	335	"	455-364 " " "
308-4 3/4	21	"	"	250	"	455-364 " " "
309-4 1/2	8 1/2	"	"	370	"	455-364 " " "



20 to 24 g wt

- 0390 J. M. Vase J. M. 9 in  
Move. 325 Blower 378-395 Gather 362 each net  
U.T.W.
- 0361 10<sup>3/4</sup> J. M. Vase 24 to 25 g wt  
Move. 300 Blower 378 Fin 395 Gather 362 each net  
U.T.W.
- 0406 Vase Paste Mould.  
Move. 250 Blower 455-364 U.T.W.
- 2374 9" Vase P.M.  
move 215 wgs 455 & 455 and 75%  
U.T.W.
- 313 Vase P.M.  
move 225 Blower 455-455-364 U.T.W.
- 500/571 Vase J. M. 10" 18 g. wt  
Move. 400 Blower 378 Finishes 395 Gather  
362 each net U.P.W.
- 0402 Vase 12 in P. M. Wt. 44 g.  
Move. 130 Blower. 455-455-364 U.T.W.
- 787-9<sup>5/8</sup> Vase Paste Mould. German Sys.  
Move. 100 Blower 455-455-364. U.T.W.
- 789-7<sup>3/4</sup> Vase P. M. German Sys.  
Move. 100. Blower 455-455-364. U.T.W.
- 798 9" Vase P. M. ~~German Sys.~~  
Move. 185 Blower-455-455-364 U.T.W.
- 799 12" Vase P. M.  
Move. 105 Blower 455-455-364 U.T.W.

- 782 8" Vase J. M.  
Move. 300 Blower. 3.75 Fin 3.95 Gather 302  
each plus 60¢ each for cleaning off. U.T.W.  
25¢ extra for finishes on P. Edgt.
- 783 10" Vase J. M.  
Move. 250 Blower 3.95 Fin. 3.95 Gather 302  
3.16 each. plus 60¢ each for cleaning off  
U.T.W. 25¢ extra for finishes on P. Edgt.
- 402 12" Iron Mould. Vase  
Move. 200 Blower 3.95 Fin. 3.95 Gather  
3.16 each. Plus 60¢ each for cleaning off.  
U.T.W. 25¢ extra for finishes on P. Edgt.
- 1287 10 in Vase move 225 Paste mould wgs  
1288 12" " move 175 Paste mould wgs  
1250 6" " " 375-378 two Get 302+60¢  
for cleaning off U.T.W. no 5% loss  
1009 6 in oval Vase move 325-378 two Gath  
302+60¢ cleaning of U.P.W. no 5% loss  
1251 8 in Vase move 3.25 Blower 378 two  
gath 302+60¢ clean off U.P.W. no 5% loss  
1252 10 in Vase move 250 blower 5.05  
blocker 4.43 ball gather 3.45 U.P.W.  
1253 12 in Vase move 225 Blower 5.06  
blocker 4.48 ball gath 352 U.P.W.  
1008 12 in Vase oblong move 200 blower 506  
blocker 4.48 ball gath 352 U.P.W.  
3400/17 12 in Vase move 185 blower 5.06 Block  
448 ball gath 352 U.P.W.  
3400/23 10 in Vase move 250 blower 505 blocker  
443 ball gath 345 U.P.W. no 5% loss



- 1242 10 in vase move 250 blower 505 blocker  
443 ball gath 345 U.P.W. no 5% loss
- 1243 10 in vase move 250 blower 505 blocker  
443 ball gath 345 U.P.W. no 5% loss
- 1130 11 inch cast foot iron mould vase  
move 225 - Blow 378 two gath 302 plus box foot caster  
\$4.55 foot straightener 3.00 U.P.W.
- #1228 10 in oval vase move 165 blower 505  
block 4.43 ball gath 345 U.P.W.
- 1292 12 in vase <sup>(more)</sup> 178 two blow 455 gath 364 U.P.W.

- 4oz Inverted Show Jar Finished J.M.  
move 550 Blow 340 - 355 + 2 Gath 272 each  
50% loss Unlimited Turn work.
- 042 Round Jar Ribbed U.P.W.  
move 200 Press 449 - 404 - 359
- 0256 Round Jar  
move 175 - - 499 - 449 - 399. U.P.W.
- 0291 Ether Jar Iron mould  
move 400 - wage 340 - 272 U.P.W. loose Saps
- 2800/59 Jar 263.  
move ~~325~~ 325. Presser 499 - 499 - 399  
U.P.W.
- Stratford Pickle Jar  
move
- Bosworth Jar  
move 850 wage 358 - 286 U.P.W.
- No 4 Disicator Jar Castorplum  
move
- No 5 Spec. Jar  
move
- No 6 Spec Jar.  
move
- No 17 Round Jar  
move



No 100 16oz Condiment Jar.  
Move.

0183 Jar optic machine  
Move. 950 Machine Wage.

30 4x4x8 Battery Jar  
Move 300 List More + Wage.

30 2 1/4 x 4 x 6 Battery Jar  
Move.

Woodworth Jar  
Move. 800 383-306 w PW

Strathford Rose Jar 1924  
Move 325 499-499-399 w PW

9 1/4 x 16 Iron Mould Jar 9 to 9 1/2 weight  
Move 85 - 505-415 Each w PW. 5% loss

3. Display Jar J. M.  
Move. 225 Blower 420-396 each 5% loss  
u T.W.

510 26oz Rose Jar J. M.  
Move. 275 Blower 377- Gather 362 each net  
u P.W.

601 1/4 lb Candy Jar Flat Foot  
Move 650 Presser 398-358-318

Mitea Jar Caster Place.  
Move. 15 doz per turn 3rd Class wages

2720 1 3/4 Door Knob made on Valve  
Move 700 Press 358-322-286  
unlimited Turn Work. Finished

3103 Knob 4 on Box  
Move

3104 Knob 3 on Box  
Move

No 10 Knob 1/4 in  
Move 850 Wage 358-322-286 u P.W.

523 1/4 in Knob.  
Move

500 1/4 in Knob  
Move

0347 Knob with hole Octagon  
Move 540 Presser 398-318 u T.W.

431 1/2 Furniture Knob 5 on box  
Move. 550 boxes. Presser 398-318 u P.W.  
Polished on patent hole shop not to stand  
loss that is not their fault

2748 Cigar Jar J. M. 48 oz  
Move 325 Blower 378 Finisher 395-  
2 Gather each 362 net 5% loss.

2234 9oz Std. Jam Jar Pull Stem  
Move 335 Plain-305 Optic Blower 381-381  
75% u T.W.



Opal Soap Container 13oz weight  
move

0338 Machine Jar.  
Move. 525 Presser 400-320 U.T.W.

0408 Machine Jar  
Move. 475 Presser 400-320 U.T.W.

0419 Woodworth Jar Machine Made  
Move. 850 with 1 mould 1000 with 2 moulds  
Presser 400-320 U.T.W.

0346 Jar Machine Press  
Move. 1050 Press-400-320 U.T.W.

2 and 2 1/4 inch Rotary Knobs. # 2756-2757  
2758-2751-2752-2755-2745. Presser  
3.95 Gather 318 each. U.T.W.  
Move. 1200.

885 Cigarette Jar  
Move. 400 Presser. 4.38-394-350. U.T.W.

1025 Cigar Jar. J. M.  
Move. 325 Blower. 3.78 Gather 302 each  
Plus. 60¢ for cleaning off. U.P.W.

894-895-896-897 Jar. J. M.  
Move. 575 Blower 3.78 Finisher 3.95 Gatherer  
302 each plus 60¢ each for cleaning off  
U.T.W.

616 Balsam Bottle Cap unfinished C.F.  
Move 1000 Press 345-276 Unlimited Price Work

2800/237 Night Bottle Cap  
Move

2949# 14-15 Base  
Move 300 Head Shop wages

431 Furniture Knob 1 1/2 in 3 on B of  
Move. 450 Mould full Press. 398-318  
When run through glazer, cover by minor  
Regulation in list U.P.W.

431 1/2 Knob 3/4 in 5 on B of  
Move 550 Bases Press. 398-318. U.P.W.  
When run through glazer, such in minor  
Regulations govern loss.

100 Condiment Jar Machine.  
Move. 875 Presser. 4.00 Gather 320 U.T.W.

507 Rose Jar J. M.  
Move. 275 Blower 3.78 Gather 302 each  
Plus. 60¢ each cleaning off. When made optic  
Optic Rule to Govent.

882 Tobacco Jar. J. M.  
Move. 440 Blower. 3.78- Gather 302 each  
Plus 60¢ for cleaning off. U.P.W.

0489 Jar. J. M.  
Move. 475 Blower. 3.78 Gather 302 each  
Plus 60¢ for cleaning off. U.P.W.



No 20 Bobshade Large <sup>mm</sup> 575 No 19 small <sup>mm</sup> 600  
398-358-318 U.P. W

## Atomizers

010 Atomizer Press Finished  
Move 650 Press 345-311-276  
unlimited Piece Work 9474

051 Atomizer Paste Mould  $1\frac{1}{4}$  oz Cap.  $5\frac{1}{4}$  High 3g weight  
Move 325 Blower 366 Foot Caster 366 Gath 274  
unlimited Turn Work.

052 Atomizer Paste Mould 2oz Cap.  $5\frac{3}{4}$  High 4g weight  
Move 305 Blower 366 Foot Caster 366 Gath 274  
unlimited Turn Work.

4003 Bottle Pull Stem  $\frac{1}{2}$  oz Cap.  $5\frac{1}{4}$  in high 2g weight  
Move 350 - 366-366-750po WTW

0312 Cologne Bottle P Stem  
Move 335 - 423-423-750po WTW  
100po off when made from Dense Colors

079 Bottle or Atomizer  
Move

0311 Cologne Bottle P Stem <sup>100po on dense colors</sup>  
Move 335 423-423-750po WTW

080 Bottle or Atomizer

208  $\frac{2}{4}$  oz Cologne P Stem WTW <sup>100po on colors</sup>  
Move 290 423-423-750po Fin 499

076 Bottle or Atomizer

060 Bottle or Atomizer  
Move

199 1oz Cologne P Stem WTW <sup>100po colors</sup>  
Move 305 423-423-750po Fin 499

207  $1\frac{1}{2}$  oz Cologne P Stem WTW <sup>100po colors</sup>  
Move 305 423-423-750po Fin 499



061 Bottle Atomizer  
move

053 Atomizer Bottle  
move

062 Atomizer or Bottle  
move

0354 Bottle Cologne Pull Stem J. M.  
move. 325 Blower 423-423-75% A. T. W.  
10% less for non-transparent colors.  
4 hrs work.

0366 Bottle Pull Stem  
move. 325 Blower 423-423-75% A. T. W.

0356 Bottle Pull Stem  
move. 325 Blower 423-423-75% A. T. W.  
10% less or more in non-transparent colors.

0428 Atomizer J. M.  
move. 900 Blower 336-Gathers 2.69 each Plus  
60¢ for cleaning off. A. P. W.

0483 Atomizer Pull Stem  
move. 370 Plain 335 Optic Blower 4.23-4.23  
75% A. T. W.

1917/12 1/2 Block Mould Cream

138 Berry Cream 75 10 oz  
move

1917/118 Handled Footed Cream or  
move 550 Wage 394-355-355-315 A. T. W.

1917/111 Boat Cream  
move 550 wage 394-355-355-315 A. T. W.

Straw Berry Cream No 21  
move. 750 398-358-318 A. P. W.

4000 Berry Cream  
move

1917/14 Cream.  
move

Straw Large Cream  
move 550 wage 358-322-284 A. P. W.

4071 Footed Cream  
move. 575 Presser 398-358-323-318. A. P. W.

# 1 Centennial Cream Cup Foot  
move. 550 Presser. 438-394-394-350. A. T. W.

867 Cream Machine  
move. 550 Presser. 438-394-394-350. A. T. W.



3400

68 Cream

Move 3.98 - 3.58 3.23 - 3.18 U. J. W.

650

3400 Cream

16

Move

600 3.98 - 3.58 - 3.58 - 3.18 U. J. W.

953 Cream or sauce <sup>more</sup> ~~foot~~ 525-438-394-323-350<sup>4.94</sup>814 Centennial 77d cream <sup>in</sup> 500-398-2 fin 357-318-2 P. W.816 77d hand led cream <sup>in</sup> 500-398-358-323-318-448 2 P. W.3400/98 <sup>iron mould cream</sup> 450-3.78-3.02-3.02+60¢-395-4.48-U. J. W.

1917/12 1/2 Block mould Sugar

Move

2800/242 open sugar

Move 560 398-358-318 U. J. W.

138 Berry Sugar 7610 of

Move

1917/16 Sugar

Move

2970 Sugar

Move

4071 Footed Sugar

Move. 575 - Pussen 398-358-323-318. U. J. W.

# 1 Centennial Sugar Cup Foot

Move. 550 Pussen. 438-394-394-350. U. J. W.

930 Sugar

Move. 489 Pussen. 3.98-358-318. U. J. W.

867 Sugar Machines

Move. 550 Pussen. 4.38-3.94-3.94-350. U. J. W.

813 Footed Sugar Sifter Machines

Move. 475 Pussen. 4.00-90% - 80% U. J. W.

0484 Hld. Sugar Server Machines

Move. 400. Pussen. 400.-90% - 80% U. J. W.

1105-1120 Cocktail Shaker. J. W.

Move. 300 Blown 395 Lathers 3.16 each plus  
60¢ each cleaning off. U. J. W.



$\frac{3400}{68}$  Sugar

More 650. 3.98-3.58-3.23-3.18 U.T.W.

$\frac{3400}{16}$  Sugar

More 600 - 3.98-3.58-3.58-3.18 U.T.W.

814 Centennial sug. m 550-3.98-2 pin 357-3.18 U.T.W.

$\frac{3400}{98}$  Sugar 450-3.78-3.02-3.02+60¢-3.95-4.48 U.T.W.

0507 far move 450 wages  
Blower 3.78 two gathers 3.02  
mad Iron mould U.P.W.

0504 far-move 275 wages Blower 3.78  
two gathers 3.02 U.P.W. Iron mould

1196 } Tablet far Tincture  
Bathroom } move 5.75 Wages Blower 3.78  
Bottle } two gathers 3.02 U.T.W.



18x11x6 Waste Mould Bowl German System  
 Move 46 Blower 503 Blocker 450 Gath 355  
 50% loss unlimited Turn work.

No 50 8 in Bowl Finished  
 Move.

2750 12 in Punch Bowl  
 Move

3200 10 in Punch Bowl  
 Move

2948 12 in Bowl  
 Move

2800/234 12 in Bowl on Trappie 1924  
 Move 185 499-449-499 WTW

2970 Low Crushed Fruit Bowl.  
 Move.

in Bowl  
 Move

3200 10 in Bowl 9 3/8 Deep  
 Move

Jona 8 in Bowl  
 Move 250 499-449-399-394 W.P.W.

Stratford 6" Orange Bowl.  
 Move 450. Head Shop Wages. W.P.W.



2942 Finger Bowl.

Move. 625- 398-358-318. U.T.W.

21 Large Egg Beater Bowl. U.P.W.

Move. 325 Presser 398-90-80 percent

21 Small Egg Beater Bowl

Move. 375 Presser 398-90% - 80% U.P.W.

24 Egg Beater Bowl.

Move. 400-Presser 398-358-318 U.P.W.

735 12" Orange Bowl

Move. 225 Presser 4.99-449-399. U.P.W.

732 Hexagon Oblong Flange Bowl.

Move. 250 Presser-4.99-4.49-399. U.T.W.

751 8" Orange Bowl.

Move. 240 Presser. 4.99-4.49-399. U.T.W.

752 10" Orange Bowl

Move. 200 Presser 499-449-399. U.T.W.

750 7" Orange Bowl.

Move. 335. Presser 499-4.49-399. U.T.W.

3075-3077-3085 Finger Bowl Pull Stem

Move. 300 Plain 270 Optic Blower. 4.23-4.23-75%  
U.J.W.

916 Gravy Bowl

Move. 500 Presser 4.38-3.94-3.50. U.J.W.

1835 Oval Bowl

Move. 175 Presser 4.99- Gather 3.99. Finisher  
on 839 and 840 Shape 4.74- on 841 shape 4.99  
U.T.W.

1125 Bowl

Move. 185 Presser. 4.99 Gather 3.99

Finisher on Cabrette Shape. 4.99

" " Plate " 4.99

" " P. Edge " 4.74

U.T.W.

11650 Three Toed Bowl

move 250 wages presser

499- Finisher 4.49 Gather

399 U.T.W.

3400 Four toed may. bowl

Move Presser 4.38-3.94-3.50 U.J.W.

525

1240 Four toed orange bowl.

Move

225 Head shop wages. U.J.W.

1152-8in deep 3 toed-350 head shop wages U.J.W.

Mt Vernon or Stafford bowl 499-449-448-399

solwer or cabinet shop finisher 4.99 U.P.W.

No. 29 Victorian Bowl - Move 425-

4.99-4.49-3.99 U.J.W. 2 finisher-4.49

No. 41 Move 425 wages - 4.99-4.49-4.49-

3.99- U.J.W.

3400/41 frappe 625-398-3.58-3.18-U.J.W.



2800/37 Ind Buttes  
 move 900 wage 398-358-318 U.P.W.

1917/14<sup>4</sup> Ind Buttes  
 move 900 398-358-318 - U.P.W.

0208 4in Buttes  
 moves 775 398-358-318 U.P.W.

920 Buttes Drainers  
 move. 750 Prison. 3.98-3.18. U.P.W.

3400/52 Buttes  
 move 675 3.98-3.18 U.P.W.

3400/52 Buttes finished <sup>m</sup> 585 398-358-318 U.P.W.



1044 Swan  
 move 175 Presser 4.99-4.49-3.99 U.T.W.

1040 Swan  
 move 725 Presser 3.98-3.58-3.18 U.T.W.

1045 Swan  
 move 125 Presser 4.99-4.49-3.99 U.T.W.

1043 Swan  
 move 300 Presser 4.99-4.49-3.99 U.T.W.

1042 Swan  
 move 425 Presser 4.38-3.94-3.50 U.T.W.

1041 Swan  
 move 650 Presser 3.98-3.58-3.18 U.T.W.

more Turkey  
 175 Presser 4.99-4.49-3.99 U.T.W.

1167 Shaker Salt <sup>Press</sup> 1 mould turning out boy.  
 move 625 - wage 345-276 W.P.W.

1201 Ind Salt 2 moulds 1200  
 move 1080 Press one mould unfinished  
 made 882 loss 0 383-306 W.P.W. C.F.

013 Salt J.M.  
 move.

2800/38 Ind Salt  
 move

1168 Shaker Salt Press  
 move 588 383-306 W.P.W.

1014 Salt Machine  
 move 1000 400-320 50% loss

1011 Salt Machine  
 move 900 400-320 W.T.W.

1025 Salt Machine  
 move 1100 400-320 50% loss

Medium Alder Salt  
 move.

2636 Sugar Shaker  
 move 750 400-320 50% loss

1015 Shaker Salt Machine  
 move 950 400-320 50%



1010 Shaker Salt Machine  
move 950 400-320 5% loss

1171 Shaker J M  
move

1175 Shaker J M  
move

1174 Shaker J M  
move

1177 Shaker J M  
move

Individual Salt stuck up one mould

972

Strc footed Ind Salt 2 Handles Plain Edge  
move 850 398-358-358-318 U P W

0321 Shaker

move 900 - 336 - <sup>blow</sup> Lather 269 each Plus  
60<sup>+</sup> for cleaning off.

1202 Salt Ind Pressed. one mould  
move 1080 383-306 U P W.

0322 Shaker J M.  
move 900 336-296 Plus 60<sup>+</sup> Cleaning

020 Shaker J M.  
move. 900 336-296 - 5% Loss U T W.

014 Shaker J M  
move 900 336 - 296 - ~~5%~~ U T W.

606 Ind Salt Dip  
move. 1080 with 1 mold. 1200 with 2 moulds  
Presser 383-345-306 U P W. Workman to  
work 2 moulds if possible to do so.

398 Footed Shaker  
move. 775 Presser. 3.98-358-318. U T W

397 Footed Shaker  
move. 800 Presser 3.98-358-318. U T W

396 Footed Shaker  
move. 750. Presser 3.98-358-318. U T W

890 Shaker Footed  
move. 700 Presser. 3.98-358-318. U T W

395 Shaker Footed  
move. 700 Presser. 3.98-358-318. U T W.

021 Salt J M.  
move. 900 5% Loss. U. J. W.

716 Shaker Machine  
move. 900 Presser. 4.00-8%. U. T. W.

0515 <sup>sup</sup> Salt-move 800 Blow 336 two gath 269+60 U P W.  
3400 individual salt-m 850 383-345-306 U P W  
if finisher is required to finish other shape his wages  
shall be taken up.

Salt tops two on a box 1050 moulds full three moulds  
398-318 U T W

3400/18 Ftd shaker <sup>m</sup> 700-398-358-358-318 U P W

0525 small shaker <sup>m</sup> 800-336-269+60 U P W



34<sup>100</sup>/<sub>36</sub> Jtl salt - 750 - 3.98 - 3.58 - 3.18 - U.J.W.  
 34<sup>100</sup>/<sub>37</sub> " " - 700 - 3.98 - 3.58 - 3.18 - U.J.W.  
 No. 24 Mt. Vernon salt - 972 - 3.83 - 3.45 - 3.06 U.P.W.X

2371 10 in Vase

move

Stratford 7 in Vase 1924 23 1/2 oz weight  
 move 475 438 - 394 - 350 wPW

53 Stratford 7 in Vase

move

made 325 loss 49

J.C.

44 Stratford 10 in Vase

move 375 449 - 449 - 399 wPW

made 282 loss when Cuffed Finisher 499 J.C.

1917/431 Auto Vase

move

2352 4 in Vase Punch Shop

59 Auto Plain 64 optie

184 12 in Vase P. M.

move move. 105 Blower 4.55 - 4.55 - 382 a TW

187 10 in Vase P. M.

move

190 12 in Vase P. M.

move

191 12 in Vase P. M.

move

181 14 in Vase P. M.

move 75 Blower 4.85 - 4.85 - 382. a TW



179 vase. 7 $\frac{3}{4}$  P.M.  
move.

200 7in Vase P.M.  
move

201 8in Vase P.M.  
move

203 8in Vase P.M.  
move.

stra 7 Vase Press 23oz  
move.

stra 10 in Vase. 35oz  
move. 375. Presser 499-449-399-700 Fin.

449. When finished Cup shape. Finisher 499.

2750 7in Vase.  
move. 475-438-394-350. 2.P.W.

Finisher machine made Cup shape. 438

2800/209 Auto Vase 9in  
move.

2800/209 7in Auto Vase.  
move. 525- 398-358-318 Q.P.W.

2800/238 Auto Vase  
move.

2357 10in Vase 31 to 35oz  
move 163 average Blows 2 437 Bath 344

187 $\frac{1}{2}$  14in Vase 65 to 68  
move 85 Blow 2 437-344

191 $\frac{1}{2}$  12 Vase 53 to 56oz  
move 95 Blow 2-437-344

184 $\frac{1}{2}$  12 in Vase 45 to 48oz  
move 105 Blow 2-437-344

190 $\frac{1}{2}$  12 in Vase 53 to 56  
move 95 Blow - 2-437-344

2970 7in Vase  
move.

185-186-188- Iron Mould. Vases to  
be worked to lamp Column. list 5%  
loss on all colors.

stra 5" Squat Vase  
move 500. Press. 398-358-323-318. 2.P.W.

stra 6" Squat Vase  
move. 400. Press. 438-394-323-350 2.P.W.

stra 7" Squat Vase  
move. 350. Press. 499-449-348-399. 2.P.W.

4061 Square Auto Vase  
move. 475. Press. 462-413-402. Black. 2.P.W.

2355- 8" P Stem Vase  
move. 335 423-423-75% Q.P.W.

2355-10" P Stem Vase  
move. 305 423-425-75% " "

2355 12" P Stem Vase "  
move 270. 423-423-75% " "

10% less on these vases on dense colors



All lamp columns made out of non-transparent colors to be worked to theopal lamp column list in P.W.

274 10 in Laper Vase Pull Stem  
Move 305 Blower 423-423-75% in J.W.

569 1/2 Vase J. M. 569 net  
Move 120 Blower 420 2 Galhus 396 each net.

2366 8" Vase Pull Stem  
Jade Green Glass only with 3/4 foot  
10% less than regular move.

0379 Vase Pull Stem in J.W.  
Move 370 Blower 351-75% 2 man shop without foot.

Martha Washington / 18 Vase Height  
Height 11 5/8 in. Cast foot. Move 275  
4.99-4.49-3.99-ft Center 4.99-3.58  
W.J.V.

1917/47 5 in Comport W 4 1/16 D 3 5/8 L 1 5/16

Some Comport  
Move 250 499-449-399-394 in P.W.

1917/46 6 in Comport Low Foot W 5 9/8 D 4 3/8 L 1 in  
Move 315 499-449-449-399 in P.W.  
made 257 loss 22 J.C.

1917/45 7 in Comport Low Foot W 7 5/16 D 4 3/8 L 1 1/2  
Move 235 499-449-449-399  
made 276 loss 71 J.C.

1917/46 5 in High Foot Comport  
Move 400 Wage 449-404-404-359 in P.W.

1917/47 6 in High Foot Comport  
Move 325 Wage 449-404-404-359 in P.W.

1917/48 8 in High Foot Comport  
Move 260 Wage 449-404-404-359.

2970 10 in Low Foot Comport in P.W.  
Move 125 Press 449-404-359

2800/48 Low Foot Comport  
Move 600 Press 358-322-286



2340 6 in Comport

move

Stratford 4 1/2 in Comport w 4 1/4 H 3 1/2 Leg 3 3/8 <sup>Foot 3 1/4</sup>

move

made 434 loss 57 JH

Stratford 4 1/2 Low Foot Comport w 4 1/2 N 4 1/2 L 1 1/2 F 3/16

move. 550 - Press. 398-358-358-318. U.P.W.

Stra 5 in Foot Hall. Comport

move.

Stra 4 in Comport

P Ring

move 675 - Press. 398-358-358-318 U.P.W.

Stra 4 in Comport

Sea Ring

move

4076 5 in Comport.

move.

255 6 in Comport High Foot Leg 4 in

move. 300 499-449-449-399 U.P.W.

51 7 in Low Foot Comport.

move

254 4 3/4 Comport Press

move 550 438-399-399-350 U.P.W.

Straightening boy to be furnished if possible

260 7 3/8 Comport. P Stem U.P.W.

move 85 455-455-75apo

10 apo off Hense Colors

263 9 1/8 Comport P Stem

move 72 455-455-75apo U.P.W.

10 apo on Hense Colors

258 10 in Comport Pull Stem

move 72 455-455-75apo U.P.W.

10 apo on Hense Colors

262 8 1/2 in Comport Pull Stem

move 85 455-455-75apo U.P.W.

257 8 1/2 in Comport Pull Stem

move 90 455-455-75apo U.P.W.

10 apo off Hense Colors

1917, 148 - 7" Comport to Silver. Move. 300

Presser 499-449-449-399. U.P.W.

1917-49-8" Comport to Silver. Move 260

Presser 499-449-449-399. U.P.W.

2942 Finger Bowl.

move 625- 398-358-318 U.P.W.

63 Comport # 2 Stem

move. 400 Presser 499-449-449-399.

63 Comport # 3 Stem

move. 500 Presser 499-449-449-399

47 Comport # 2 Stem

move 400 Presser 499-449-449-399

47 Comport # 3 Stem

move. 450 Presser 499-449-449-399



4071 6" Comfort  
 Move. 475 Press 499-449-449-399 Q.T.W.  
 Finish 25¢ extra on flat rim

6" Stratford Orange Bowl  
 Move. 450 Press 499-449-399. Q.P.W.

531 Tall Comfort Cup Foot  
 Move. 325 Press. 499-449-449-399. Q.T.W.

533 Comfort Move. 495 Cup Foot  
 Press 438-394-394-350 Q.P.W.

871 Comfort Cup Foot  
 Move. 550 Cup foot wago. Worked F.W.  
 until mould is in working order and  
 thus works. P.W.

{ 3400/14 cast foot comfort move 350-499-449-399  
 { 1090 " " 455-358 Q.P.W.

3400 no 3 comfort move 225-499-449-399  
 3400/30 Cast foot Comfort two hld <sup>made</sup> 225-499-449-399-499-350  
 Q.P.W. (49)

531 Comfort Cast foot  
 Move 350. - 4.99-4.99-3.99-4.55-3.58 Q.P.W.

## Candlestick

2862 Tin Candlestick Finished  
 Move 500 Press 358-322-286 Q.P.W.

Lois Candlestick 10in Finished  
 Move.

made 236 loss 7

J. H. G.

218 9in Candle Stick Stem Shop  
 Move 200- 366-366-75% Q.T.W.

219. 10in Candle Stick Stem Shop  
 Move 250 423-423-75% Q.T.W.  
 10% off when made from House Colors

216 10in Candlestick Hollow Foot Stem Shop  
 Move. 165 wago 425-318. Q.T.W.

220 9 3/8 in Candlestick Pull Stem  
 Move 275 423-423-75% Q.T.W.  
 10% off when made from House Colors  
 222 6in Candlestick  
 Move 350 438-394-394-350 Q.P.W.

225 9in Candlestick  
 Move 200 " 438-394-394-350 Q.P.W.

226 9in Candlestick  
 Move 250 438-394-394-350 Q.P.W.

2861 7in Candlestick  
 Move.

230 7in Candlestick  
 Move 300 398-358-318 Q.P.W.



236 8 in Candlestick  
 Move 450 398-358-318 U.P.W.  
 239 7 in Candlestick  
 Move 500 398-358-318 U.P.W.  
 2800/110 7" 2 Ald. Candle Stick  
 Move 235. Presser 438-394-358-350  
 U.P.W.

Dolphin Candlestick  
 Move. 300. Listed wages 1 mold U.P.W.

436. 938 Candlestick  
 Move. 375 Presser 438-394-350

634 Candlestick  
 Move. 525 Presser 438-394-394-350 U.P.W.

# 63 Doric Candlestick with Hole  
 Move. 225 - Cup Foot Wages. U.P.W.

635 Candle Stick 5 in  
 Move. 550 Presser 398-358-318 U.P.W.

637 Candle Stick 3 in  
 Move. 675 Press. 398-358-318 U.P.W.

639 Candlestick 4 in  
 Move. 600 Presser 398-358-318 U.P.W.

628 Candlestick  
 Move. 525 Presser. 4.38-394-350. U.P.W.

629 Candlestick unfinished  
 Move. 800 Presser. 3.98-318 U.P.W.

627 Candlestick  
 Move. 500 Presser 4.38-394-394-350  
 U.P.W.

638 3 Holder Candlestick  
 Move. 225 Presser 4.99-4.49-4.49. 3.99  
 U.P.W.

825 3 Holder. Candlestick  
 Move. 350 Presser. 4.48-4.03-358- U.P.W.

1050 Candle Holder  
 Move. 650 Presser. 8.98-318. U.P.W.

715 Candlestick unfinished.  
 Move. 675 Presser. 3.98-318. U.P.W.

625 Candlestick  
 Move. 675 Presser. 4.38-3.94-350. U.P.W.

1155 Three tiered candle holder  
 Move 398-358-318 U.P.W.  
 625

647 Two holder candlestick  
 Move 235 Presser 4.99 - two finishers 4.49  
 each gatherer 3.99. U.P.W.

636 9 inch Candlestick  
 move 200 Presser \$4.38 - finisher \$3.94  
 foot finisher \$3.94 gatherer \$3.50 U.P.W.

646 5 inch candlestick move 3.50  
 Presser 438 two finishers 394  
 gather 350 U.P.W.



- 878 Candlestick  
 more 525 4.38 - 2 fin 3.94 - 350 U.I.W.  
 5
- No 3 Centinal Candle stick 10 inch high  
 more 180 head shop wages U.P.W.
- 1269 10 inch candle stick <sup>more</sup> 180 head  
 shop wages U.P.W.
- 1192 Candle stick more 358 - 438 - 394 - 350  
 foot caster 455 - foot straight 358 U.P.W.
- 1209 one leaf candlestick <sup>m</sup> 275 448 - 403 - 403 - 358 U.P.W.
- 1273 Candlestick <sup>m</sup> 180 - 499 - 2 fin 449 - 399 U.P.W.
- 1271 " " 275 - 438 - 2 fin 394 - 350 U.P.W.
- 1271 leaf 2 holder candle <sup>m</sup> 200 - 499 - 2 fin 449 - 399 U.P.W.
- 1269 Candlestick <sup>m</sup> 180 - 499 - 2 fin 449 - 399 U.P.W.
- 1272 " " 225 - 499 - 2 " 499 - 399 U.P.W.
- 1229 " " " antique Antigua 525
- 1274 Candlestick  
 more 130 Presser 4.99 - 4.49 - 4.49 - 3.99 U.I.W.  
 3011 candlestick with lotashade 3011 candlestick more 400  
 wages 3.98 - 3.58 - 3.18 - 4.55 - 3.58 U.P.W.
- 1269 8 3/4 in - 235 - 4.38 - 3.94 - 4.55 - 3.58 - 3.50 U.I.W.
- No. 36 Victorian 8 3/8 in 275 - 4.38 - 3.94 - 4.55 - 3.58 - 3.50 U.I.W.
- 1273 9 3/8 - 235 4.38 - 3.94 - 4.55 - 3.58 - 3.50 - U.I.W.
- No. 36 <sup>m</sup> 200 4.38 - 3.94 - 3.94 - 3.50 U.I.W. until settled
- 1307 3 holder 225 - 4.99 - 4.49 - 4.49 - 3.99 - U.I.W.

- 50 - 2 Gallon Fish Globe Paste Mould  
 more  
 Finished
- 25 - 3 Quart Fish Globe Iron Mould 2 lbs weight  
 more 350 Blower 340 - 355 - 272 Each  
 5 ops Loss Unlimited Turn Work Finished



Amber Salt Mouth Cap 64g 30g weight  
 Move 228  
 Made in Paste Mould. Finished  
 50ps loss u.L.T work

Amber Salt Mouth Cap. 64 48g weight  
 Move 180 412 $\frac{1}{2}$ -371-351-289.  
 Made in Paste Mould Finished  
 50ps loss Unlimited Turn work 1

No 1 Estman 1 $\frac{1}{2}$  Gal. Salt Mouth  
 Move

#1 Onyx Ball Diam 1 $\frac{1}{4}$  in  
 Move. Polished 1000 Not Polished 1050  
 Blower 364 Gather 309 each Cleaning off by  
 furnished u.T.W.

#3 Onyx Ball Diam 1 $\frac{1}{2}$  in  
 Move. Polished 950 Not Polished 1,000  
 Blower 364 Gather 309 each. Cleaning off  
 Bay furnished u.T.W.

#5 Onyx Ball Diam 2 in  
 Move. Polished 900 Not Polished 950  
 Blower 364 Gather 309 each. Cleaning  
 off by furnished u.T.W.



4 in Desiccator jar

move

Snapped up. Castor Place

5 in Desiccator jar

move

Snapped up Castor Place

6 in Desiccator jar

move

Snapped up Castor Place

0358 Percolator J. M.

Move. 250 Blower 378-Gather 362 each  
net

Special Percolator Castor Place

Move. 13½ doz per turn. 3rd Class Wagon.

0380 Percolator J. M.

Move. 225 Blower 395. Gather 316 each  
Plus cleaning off wages. On T W

0413 Percolator J. M. 23 doz net  
Move. 315 Blower 378. Gather 362 each  
net. When made special order made to  
govern. J. P. W.

0412 Percolator J. M.

Move. 225 Blower 395-Gather 316 each  
Plus. 60¢ for cleaning off. On T W. 5% Tax.

0462 Percolator J. M.

Move. 235 Blower 395-Gather 80% Plus  
65¢ each cleaning off. On T. W.



0470 Percolator J.M.  
 Move. 175 Blower 4.20 Gethus 80%  
 Plus 60¢ each cleaning off. U. J. W.

0495 Loud Speaker Percolator J.M.  
 Move. 225 Blower 3.95 Gethus 3.16 each  
 Plus 60¢ each cleaning off. No 5% loss. U. J. W.

170 Syrup Machine made  
 Move 550 average 400-320. W.T.W. Halls 403

174 Syrup Machine made  
 Move. 550 400-320-448 Halls W.T.W.



2970 Tall Spoon  
move

Large Spoon  
move

4071 2 Tall Spoon Tray  
move

930 Spoon  
More 592 Presser 3-98-358-318. C. J. W.  
609 spoon and fork <sup>in</sup> 250 mould full 448-358-2, P. W.



Large Fork  
more



3 7/8 Round Auto Lense  
 move 1025 wage 449-800ps W.P.W.

3400/92 Iron mould decenter <sup>max</sup> 325 Plain <sup>wage</sup> 328-302  
 apt 416 plus 6 of Hld 499 fin 395 apt rule to gov U.P.W.  
 321760F

3400/92 Jig Ball <sup>m</sup> 350 apt rule to gov U.P.W.

1510 7oz Tumbler Punch  
 move

2800/234 Tumbler 8 1/2 oz  
 move 825 - Press 398-358-318 W.P.W.

1510 3 1/2 oz Tumbler  
 move

Georgia Tumbler  
 move 740 wage 398-358-318 W.P.W.

274 6oz Tumbler  
 move

2970 5oz Tumbler  
 move 850 wage 398-358-318 - W.P.W.

2800/207 Tumbler to Basket 12oz  
 move 625 wage 398-358-318 - 499-499 W.P.W.

274 1oz Tumbler  
 move 900 wage 398-358-318 W.P.W.

4070/33 5 1/2 oz Soda  
 move 800 wage 438-394-350 W.P.W.

Ball Tumbler, Punch Shop 1924 all colors.  
 move 560 338-270 W.P.W.

2393 8oz Tumbler Sham  
 move 525. Presser 398-358-318. W.P.W.



1510	3 <sup>1</sup> / <sub>2</sub> 02	66 Plain 71 Opt <sup>er</sup>	} Punch Shop.
1510	7 02	90 " 95 "	
1510	13 02	115 " 120 "	

Paste Mould Article 0302.  
Blower 1.60 Per 100. Catcher 80%.

3000 5% Tumbler Punch Diet. Bell Top  
wages.

550-103 Footed-Hld. Tumbler On P.W.  
Move. 650-Presser 398-358-348-318

500/122-103 J.M. Tumbler-  
Move. 650. Blower-378-362 each On P.W.

552 79 Footed Tumbler Half Cup.  
Move. 950 Presser 398-358-348-318 On P.W.

324 Bar Tumbler R. Edge.  
Move. Presser. 3.98-3.58-3.18. U. T. W.  
Finisher 25¢ extra.

1201 boxturn<sup>or whiskey</sup> <sup>more</sup> 900-398-358-318 U.P.W.

Twine Holder ~~wage 358 322-286~~  
Move 395 wage 403-363-322 U.P.W.

2880/93 Core Holder  
Move.

Large Sandwich Holder  
Move

212 Match Box Holder

600 Cigarette Holder  
Move. 600 Presser. 438-394-350 Finisher  
wage has been protested for 25¢ extra

0369 Oval Cigarette Holder  
Move. 600 Presser 398-358-318. U.P.W.

4076 Goblet  
Move. Regular Shape 700 }  
" Cone Shape 650 }  
" Flat Rim 625 }  
Presser 398-358-323-318. U.P.W.

969 Goblet  
Move. 675 Presser. 4.38-3.94-394-350. U. P. W.

212 Match holder  
Move 3.98-3.94-3.58-3.18 U. T. W.  
750.

Mount Vernon goblet 100¢.  
Move 3.98-3.58-3.23-2.18. U.P.W.  
775



2861 Tooth Pick Plugged Cup  
move. 700 398-358-318 a. P. W.

525 1/2 Cocktail Glass No foot.  
Move. 800 Prussen 397-358-318

525 Cocktail Shaker Cup Foot 24 oz  
Move. 350 Prussen 499-449-449-394.

5-25 3/4 oz Cocktail Glass Cup Foot  
Move. 765 Prussen 438-394-394-350

5-26 2 oz Cocktail Glass Cup Foot  
Move. 765 Prussen 438-394-394-350

## Jugs

2800/234 Large Jug no marks  
move 150 449-404-359 a. P. W.

2590 1/2 1/2 Gallon Jug.  
move.

2800/241 1 1/4 Jug Iron mould  
move.

0.45 Jug J. M. No Hld.  
Move. 300 Jug Vages. a. P. W.

Carafe Jug.  
Move. 250. 499-449-399. a. P. W.

3075 Jug. Paste Mould. 62 oz. Capacity  
move. 114. Blower. 455 each. Foot Caster  
4.55 Gathus 3.64 Standler. 4.85 Shuers  
4.85 On T. W.

803 36 oz Jug. J. M.  
move. 300 Blower. 4.04 Handler. 4.99. Fin. 3.95  
395. Gathus 3.02 Plus. 60¢ for cleaning  
off. a. P. W.

936 65 oz Jug J. M.  
move. 250. Blower. 4.04 Hld. 4.99. Fin. 3.95  
Gathus 302 each. Plus. 60¢ for cleaning  
off. a. P. W.

935 68 oz Jug J. M.  
move. 250. Blower. 4.04 Hld. 4.99. Fin. 3.95  
Gathus 302. Plus. 60¢ each for cleaning  
off. a. P. W.



802 10 3 Jug. 9. M.  
 Mon. 4.75 Blow. 4.04. Hld. 4.48. Fri. 3.75  
 Salthus 302 each. Plus. 60¢ for cleaning  
 off. U.F.W.

3145 Jug 80 oz Cap.  
 move 2.50 Opt. Jug wages.

3400/38 jug ball choke <sup>mm</sup> 225-505-443-345-395 U.F.W.  
 3400/27 <sup>mm</sup> 250-505-443-345-395 U.F.W.

0529 Jug. Move 2.75. Regular iron  
 mould German system  
 wages.

3400/14 Iron mould Jug. German system  
 wages. U.F.W. move 2.50

2800/38 oval Ind Olive weight 4oz L 3 3/4 H 3 1/4  
 move 900 wage 398-358-318. U.P.W.  
 made 820 lost 97  
 9107



{ all glass salt tops 1050 mould full or 2100  
398-318 u. P.W.

016-2 half Cylinder  
move 900 358-286 u. P.W.

6x8 Cylinder 2 in.  
move.

502-C. Opal Cylinder Punch 3x5  
move. 385. Blower 500- Gathu 353 u. P.W.  
Company agreed to pay for cords that the men could  
not see while working.



8x15 Bell Glass Cas Place  
 move 47 First Class

8x13 Bell Glass  
 move 47 First Class

Paste Mold Graduates	3 Man Shop.
1 Dram	37 Doz. Per Turn
2 "	" " " "
1/2 g.	36 " " "
1 "	34 " " "
2 "	31 " " "
4 "	26 " " "
8 "	22 " " "
16 "	17 " " "
32 "	12 " " "

Blown 366 Foot Paste 366 Gather 258  
 Blown - Foot Paste wayer divided even

64 g. Graduate Paste Mould. S.S.  
 move. 108. Blown. 455 Foot Paste 455 Gather  
 364. U. T. W.

2800/41 Custard no Handle.  
 move 825 Press 358-322-286

4070 Custard  
 move 825 wayer 398-358-318 U.P.W.

494 Footed Hld. Custard  
 move. 750 Presser. 398-358-318. U.P.W.

495 Footed 2 Hld. Custard  
 move. 750 Presser 398-358-318. U.P.W.

933 Custard  
 move. 825 Presser. 398-358-318. U. T. W.

865 Custard  
 move. 825 Presser. 398-358-318. U. T. W.

865 Cream  
 move. 750 Presser. 398-358-318. U. P. W.

866 Bullion Cup.  
 move. 650 Presser. 398-358-318. U. P. W.

925 Custard  
 move. 825 Presser. 398-358-318. U. T. W.

3133/913 Custard or cup  
 move 825 398-358-318 U.P.W.

Mount Vernon custard  
 move 825 398-358-318  
 U. T. W.

842 Victoria fld Hld. Custard. 750-398-358-318-U. T. W.



2743 Cologne.  
move

206 Cologne Press 1oz  
move 600 438 499-394-350 nTW

2742 3oz Cologne J.M  
move

204 2oz Cologne J.M  
move

205 4oz Cologne J.M  
move

198 Cologne  
move. 600 Presser 438-499-350 nPW

585 Cologne  
move. 600 Presser 438-499-350 nPW

586 Cologne  
move. 600 Presser 438-499-350 nPW.

0401 Bottle Pull Stem  
move. 370 Plain 335 Opter Blower 423-423-75% nTW

0402 Bottle Paste Mold.  
move. 250 Blower 455-364 nTW.

0398 Cologne  
move. 550. Presser. 438-499-323-350. nPW

2791 Coaster  
move.

0439 Cologne P. Stem  
move. 325 Blower. 4.23-423-75% nTW

0440 Cologne. P. Stem  
move. 305 Blower 4.23-4.23-75% nTW

0441 Cologne P. Stem  
move. 335 Blower 4.23-423-75% nTW

0438 Cologne P. Stem  
move. 370 Blower 4.23-423-75% nTW

0364 Cologne P. Stem  
move. 370 Blower. 4.23-423-75% nTW

0478 Cologne Pull Stem  
move. 305 Plain 275 Opt. Blower 4.23  
Foot Coaster 4.23. Gathu 75% nTW.

0477 Cologne Pull Stem  
move. 335 Pl. 305 Opt. Blower 423-423  
75% n. J. W.

0499 Cologne Pressed Stem J. M.  
move. 475 Blower. 4.23-4.23- Gathu 75%  
Foot Finisher 2.70 n. T. W.

0487 Cologne Press. Stem  
move. 475- Blower. 4.23-4.23- 75% Foot  
Finisher 2.70 n. T. W.



1917/101 9 in Pickle  
move

1917/511 Pickle  
move

Stra 10 1/2 in Pickle  
move

1917/100 Pin Pickle.  
move

1917/52 7 in Pickle  
move

1917/57 9 in Pickle  
move

1917/109 9 in Pickle  
move

Stra 10 1/2 in Pickle  
move

907 9" Pickle  
move. 600 Presser. 3.98-3.58-318. Q. T. W.

1082 9" Pickle  
move. 525 Presser. 3.98-3.58-318. Q. J. W.

1067 9" Pickle Partition  
move. 475 Presser. 4.38-3.94-350. Q. T. W.



3400/86 Pickle 2 hld. 1 mold. 8 inches  
More 5.35 - 3.98 - 3.58 - 3.18 U. J. W.

1917/142 Fern Dish  
More



1064 8oz Pilsener Beer  
more

1064 12oz Pilsener Beer  
more

0272 Ink  
more 1050 Press 345-272 in PW

1716 Ink  
more. Press 383 Jethu 906. in PW  
No 1 Lewis ink from mould <sup>in</sup> 600-578-3027607 2, 7, 11.

No 11	Square Ink	<sup>more</sup> 300	} 3.98-3.18. U.S. V. Never get a more good.
.. 21	.. ..	400	
.. 41	Round Ink	450	



5 5/8 Base unfinished

move 450 Press 358-286

with Hole 50po off

4 1/2 Base unfinished

move 550 Press-358-286

with Hole 50po off

3 5/8 Base unfinished

move 675 Press 358-286

with Hole 50po off

100po added when 2 moulds are used



oval mustard move 700 flower 3.70  
 two gathers 285+600 2.17.11.  
 This apply to opt only.

2590 1/2 Mustard u P W  
 move 750 Press 358-322-286  
 Strc 8 oz Mustard  
 move 650 398-358-318 u P W

2970 Parfait Flat Foot  
 move 650 if mold. is in working order  
 Presser 398-358-323-318 u P W

701 Place Card  
 move 1000 Presser 383-306 u P W

0491 Figures  
 move 160 Presser 4.99-449-399 u. J. W.

1114 Figure  
 move 260-499-449-399 u. P. W.  
 u u hering 125-499-449-399 u, P, W.



2800/81 10 in Block Mould Oral u P W  
 move 415 Press 358-322-286

2800/81 9 in Block Mould Oral Spike Edge  
 move 475 Press 358-322-286

2800/81 8 in Block Mould Oral Spike Edge  
 move 575 Press 358-322-286

Stratford 10 in Oral spike Edge  
 move 435 Wage 358-322-286 u P W

Strat 8 in Oral Plain Ring  
 move 485 358-322-286 u P W

Strat 9 in Oral Plain Ring  
 move 440 Wage 358-322-286 u P W

Strat 10 in Oral Plain Ring  
 move 400 358-322-286 u P W

Stratford 9" Footed Hld. Oral  
 move 225 - Press. 499-449-399 u. J. W.  
 Foot 7/8 incher 348.

Oral 9 M. move. 135 @ 420-396 each net.  
 move ~~135~~ 135

Monkey 9 M.  
 move. 175 Blower 395-2 Gathers 376 each net  
 u. J. W.

351 644 Oral:  
 move. 650 Press 398-357-318. u P W



0394 Large Oval J. M.  
 Move. 450 Blower 336 - Gather 272 each plus  
 60¢ for cleaning off. Optic Rule to govern

0393 Small Oval J. M.  
 Move 550 - Blower 336 Gather 272 each plus  
 60¢ for cleaning off. A. T. W.

428 8" Oval  
 Move. 515 Presser. 4.38-3.94-350. Q. J. W.

428½ 8" Oval With Partition  
 Move. 465 Presser. 4.38-3.94-350. Q. T. W.

429 10" Oval  
 Move. 435 Presser. 4.38-3.94-350. Q. T. W.

429½ 10" Oval With Partition  
 Move. 3.85 Presser. 4.38-3.94-350. Q. T. W.

427 6" Oval  
 Move. 660 Presser. 3.98-3.58-318. Q. J. W.

1087 9" Oval  
 Move. 475 Presser. 4.38-3.94-350. Q. J. W.

1088 10" Oval  
 Move. 4.35 Presser. 4.38-3.94-350. Q. J. W.

835-839 Oval Bowl  
 Move 175 Presser. 4.99 Gather 3.99. Finishes  
 on 839 and 840 Shape 4.74 - on 841 Shape 4.97  
 Q. T. W.

No 157 Marmalade P. Stem A. T. W.  
 Move 335 wege 330-330-75¢

154 Marmalade Machine  
 Move. 800. 400 - 320 5% Loss.

158 Marmalade Pull Stem  
 Move. 370 Plain 335 Wide Optic Blower 381  
 Foot Caster 381 - J. 75¢ A. T. W.



- Small Flower Block  
 Move 650 358-286 u.P.W.  
 4 3/8 Flower Insert  
 Move 650 398-358-318 u.P.W.  
 Flower Insert  
 Move 675 398-358-318 u.P.W.  
 2 1/2 Flower Insert  
 Move 700 398-358-318 u.P.W.  
 Flower Insert  
 Move 725 398-358-318 u.P.W.
- 2901 4" Insert  
 Move 525 398-358-318 u.P.W.
- 2901 5 1/2" Insert  
 Move 450 438-394-350 u.P.W.
- Small Clock Frame  
 Move 325 438-394-350 u.P.W.
- 0325 Barrell J.M.  
 Move 225 505-435-5% Loss u.P.W.
- 0324 Bonell J.M.  
 Move 200 505-435-5% Loss.
- 1 Barrel J.M.  
 Move 235 505-435-5% Loss u.P.W.
- Flyout traps  
 Move 300 398-318 u.P.W.

- 0134 Cupping Glass w 2 in H. 5 1/2  
 move
- 0135 Cupping Glass  
 move
- 0296 Exhaust Glass. Machine  
 move 600 Presser 400-360-320 u.P.W.
- 0297 Exhaust Glass. Machine  
 move 500-Presser 400-360-320 u.P.W.
- Fly Out Trap  
 Move 300 Press 398-318 u.P.W.
- 705 Flower Pot Saucer  
 move. Presser 383-345-306 u.P.W.



836 Flower Block Oval  
 Move 500 Presser. 4.48 - 3.58 U.T.W.

## Stoppers

197 oil Stopper  $1\frac{3}{16}$

move

206 Stopper  $1\frac{3}{16}$  <sup>lead.</sup>  $4\frac{1}{2}$  long dropper

move 600 wage 398 - 358 - 318 U.P.W.

193 oil Stopper

move 700 Wage 345 - 311 - 276 U.P.W.

17 Dec Stopper

move

Straw Pickle Jar Stop

move

2800/59 26g Stopper U.P.W.  
 move 420 <sup>1 mold</sup> 550 <sup>2 mold.</sup> Presser 383 - 345 - 306

205 Stopper dropper

move 600 398 - 358 - 318 U.P.W.

204 Stopper dropper

move 650 398 - 358 - 318 U.P.W.

207 Stopper dropper

move 550 398 - 358 - 318 U.P.W.

208 Stopper dropper

move 500 398 - 358 - 318 U.P.W.

199. Stopper Dropper

move 600. 398 - 358 - 318 U.P.W.

$1\frac{1}{2}$  Carafe Stopper

move 540. 2. Blowers 455 each G. 364 U.T.W.

315 - 16g Dec. Stopper

move 900 Blower 336 - 2 Gath 329 each U.P.W.



- 4 Pasted Mold Stopper  
 Move. 540 Blower 455-455-364 U.T.W.
- 198 Cologne Stopper  
 Move. 700 Presser 398-318 U.P.W.
- 1 Barrell Stopper 3 on Box  
 Move 425 Boxes Presser 398-318 U.P.W.
- 206  $\frac{3}{4}$  Stopper no knob  
 Move 650 Presser 398-358-318 U.P.W.
- 586 Stopper 3 on Box  
 Move. 1650 Presser 398-318 U.P.W.
- 585 Stopper 2 on Box  
 Move. 1400 Presser 398-318 U.P.W.
- 198 Stopper 2 on Box  
 Move. 1250 Presser 398-318 U.P.W.
- 0383 Stopper  
 Move. 650 Presser 398-358-318 U.P.W.
- 3075 Stopper 1 mould.  
 Move. 350 Blower 455-364. U.T.W.

- Strathford 4  $\frac{1}{2}$  in Compost. W 4  $\frac{1}{4}$  H 3  $\frac{1}{2}$  Leg 3  $\frac{3}{8}$  F 3  $\frac{1}{4}$   
 Move  
 made 434 lost 51 J.L.
- Large Spoon  
 Move 500 . Wage 403-322 U.T.W.
- Large Fork  
 Move 500 . Wage 403-322 U.T.W.
- Barrell Stand  
 Move 400-Presser 398-318 Dick M.  
 U.P.W.
- 3075/15 Stopper  
 Move. 700 Presser 383-345-306 U.P.W.
- 731 Stopper  
 Move. 725 Presser 3.83-345-306. U.P.W.
- 619 Stopper  
 Move. 725 Presser 383-345-318. U.P.W.
- 595 stopper solid peg. move 900-383-306 U.P.W.
- 3145 Stopper  
 Move 575 ~~6~~ Presser 3.83-345-306. U.P.W.
- 3400/92 Stopper  
 Move 675 Presser 3.83-345-306. U.P.W.
- 1324 Stopper  
 Move 625 Presser 3.83-345-306. U.P.W.
- 1526 Stopper  
 Move 700 Presser 3.83-345-306 U.P.W.



170 Machine Syrup Cap 903  
 More 550 Machine Wax Handler 403

2400/79 Stopper  
 More 750 Presser 3.83-3.45-3.06. U.P.W.

3400/97 Col. Stopper with dropper <sup>photo is being taken</sup>  
 More 650 Presser 3.98-3.58-3.18 U.P.W.

Locktail stopper <sup>m</sup> 400- 3.83-3.06 U.P.W.

Balsam bottle stopper with  
 or dropper.  
 More 800- 3.83-3.06 U.P.W.



99 8 in Salvans  
 more 400. 449-404-359 NWVW

707 Salvans  
 more 200 - 4.99 - 4.99 - 4.49 - 3.99. U.T.W.



Carter Carburetor Cup  
 move 600 358-286 wPW

0230 Cup.  
 Move. 575 398-318 G.P.W.

## Sines

125 in on Sines 4 1/4 diameters  
 move.

#23 Mayonaise Ladd. 2 on Box  
 move. 1200 or 600 Boxes  
 Press. 398-318. In. T.W.



1064 8oz Palmer Beers  
 Move. 450 438-394-394-350. Q.P.W.

1064 10oz Palmer Beers  
 Move. 400. 438-394-394-350. Q.P.W.

3095 Press. Stem Ware.

Gotlet Move. 400

Saucer. Champagne Move. 400

Cocktail Move. 475

Shrubet. Move. 465

Fld. Tumbler 425

Blower. 3.72 Bowl. Gathu 2.79. Stem Gathu

253 Presser. 3.72 Foot Caster 4.05 Q.T.W.

10% added to wages when a move is selected good.

3110 Press. Stem Ware

Gotlet 400

Saucer. Champ. 400

Cocktail 475

Shrubet 465

Fld Tumbler 425

Blower. 3.72 Bowl Gathu 2.79 Presser 3.72

Press Gathu 2.53 Foot Caster 4.05. Q.T.W.

10% to be added to wages when a move is selected good.

1402/45. 14 oz hld tum flat foot

Move hld 425 - presser 750 Q.T.W.

Mount Vernon 14oz stuck hld

Move hld 425 - presser 675 Q.P.W.

do not make  
 this wage  
 any more  
 work the system  
 any more

0292 Article

Move

6303 Article made on Valve

Move 300 438-394-350 Q.T.W.

0405 Turtle Machine Press.

Move. 250 Presser 400-320 Q.T.W.

10% to be added to wage when a move is selected good.

0473 Article

Move. 600 Presser. 4.38-394-350. Q.T.W.

0479 Hexagon Article

Move. 850 Presser. 3.98-3.18. Q.T.W.

0492 Article

Move. 500 Presser. 3.98-3.18. Q.T.W.



0334 Article

Move. 650 Blower 336 Gather 80% Plus 60¢  
for cleaning off. U. P.W.

0415 Article J.M.

Move. 250 Blower 378 Gather 362 each net.  
U. T.W. No 5% loss.

0422 Article J.M.

Move. 250 Blower 378 Gather 362 each net  
U. T.W. No 5% loss.

0414 Article J.M.

Move. 180 Blower 395 Gather 80% Plus  
15¢ each for cleaning off. U. T.W. No 5% loss.

3085 Stem Ware.

Waked to the listed move. and Head  
Shop wages. Applies only to fancy and  
piano legs.

0479 Hexagon Article

Move. 850 Presser. 3.98 - 318. U. T.W.

0512 Article cogwheel<sup>m</sup> 450-398-358-318 U.T.W.



065 Battle Finished. Skin Shop  
move

020 Battle I m  
move 900 Salt Wage uTW

021 Battle I m.  
move 900 Salt Wage uTW

No 19 water Battle  
move

013 Battle  
move

Small Cat and Dog Battle Iron Mould  
Mold 400 378-800ps Each uTW 50ps loss

1 1/2 Gal. Salt Mouth Bottle. Caster Place.  
Move. 22 doz Per day. 1st Class Wages.

2800-69- Water Bottle

move. 275 with 3 finishers or. 260 with 2  
finishers Press. 499-449-449-449-399. uTW.  
if new mould is O.K.

097 Paste M. Bottle

Mold. 200 455-455-364. uTW.

Small Cat-Dog IM

move. 400. 378-80% 5% Loss uTW.

076 Bottle P. M. 2 doz wt

move. 375 Blower 455-Gather 364 uTW.



- 0355 Bottle Paste Mold 1 Blower.  
 Move. 200 Blower 455-364 U.T.W.
- 0381 Bottle Pull Stem  
 Move. 335 Blower 423-423-75% U.T.W.
- 0382 Bottle P.S.  
 Move. 325 Blower 423-423-75% U.T.W.
- 0383 Bottle P.S.  
 Move. 325 Blower 423-423-75% U.T.W.
- 0401 Bottle P.S. 3g.  
 Move. 370 Plain Blower. 423-423. 75% U.T.W.
- 0364 Bottle P.S.  
 Move. 370 Plain Blower. 423-423-75% U.T.W.
- Haffey Joss. Bottle J.M.  
 Move. 800 Blower 378 gather 362 each net  
 U.T.W.
- E Bottle 2g Cap. 3g net  
 Move. 370 Blower 423-423-75% U.T.W.
- 1194 Bath Room Bottle.  
 1195 Move. 650. 3.78-3.95-two gath.  
 3.02 Plus 60 cents for cleaning of  
 U.T.W.

1323 Ban Bottle 28 oz. Move. 235 }  
 1324 " " 24 " " 2355 }  
 two Blowers 455 gather 364 upper or under 4.85 }  
 3400/99 oil bottle - 450-3.78-3.02-302+60¢-395-448  
 U.T.W.

- 0239 Globe J.M.  
 Move. 500. 378-302-Plus C.O. wages  
 a.P.W.
- 505 D Globe J.M.  
 Move. 625 wage 336-269-269 U.P.W.
- 504 D Globe J.M.  
 Move. 600 wage 336-269-269 U.P.W.
- 0300 Globe J.M.  
 Move. 575 wage 378-302-302 turn work  
 until Blower says it can be worked piece  
 50 2 Gal Fish Globe Gas. Place.
503. D. Globe, Paste Mould. J.M. Shop.  
 Move. 325-Blower 455-364. U.T.W.
- 0368 Globe. J.M. 7 inch  
 Move. 300 Blower 378 gather 302 each Plus  
 cleaning of wages. U.P.W.







2800/234 Soap Dish  
 Move 690 358-322-284 W.P.W.

326 Relish Dish ~~750~~  
 Move 665 Presser 398-358-318

2949 Lemon Dish Inf.  
 Move 775 Presser 398-318 W.P.W.

980 Cheese Dish or Napkin  
 Move 675 Presser 398-358-318 W.P.W.  
 10% added to wage when a move is selected good.

951 Toast Dish 9"  
 Move 500 Presser 448-403-358 W.P.W.

W.S. Soap Container  
 Move.

0371 4 1/2 oz Spirit Lamb J.M.  
 Move 700 Spirit " Wags

0286 Soap Container J.M.  
 Move 600 Blower 378 Gath 362 each net  
 W.P.W.



2660 Ald. Footed Sherbet  
Move. 750 - Press. 398-358-323-318. U.P.M.

3358 6oz Peg Sherbet Pull Stem  
Move. 370 Blower 381-Gather 75% U.T.W.

4071 Sherbet  
Move. 800 - Presses 398-358-323-318  
U.P.M. Straitening Boy furnished.

3400

~~3400~~ 4 in Sherbet

15

Move 750 398-358-323-318 U.T.W.  
316 sherbet flat foot tumbler bottom 800-398-358-323-318 U.P.M.

2800/486 Tall Press H Basket  
Move.

124 Basket Press Ndle.  
Move 850. 398-398-318. U.P.M.

2800/245 Basket Press Ndle 3 1/4  
Move 850. Presses. 398-398-318. U.P.M. on Plug.  
When 2 finishers are used. Finishers receive 358 each.

2800/245-4 1/2 Basket Press Ald.  
Move. 550 - Presses 398-398-318. U.P.M. on Plug.  
When 2 finishers are used finishers get 358 each.

2800/245. 6" Basket Press Ald. - <sup>when</sup> made on Plug.  
Move. 300. Presses 499-~~499~~-499-Q. 399 U.P.M.  
When 2 finishers are used finishers get 449 each.

2800/245. 7" Basket Press Ald. <sup>when</sup> made over Plug.  
Move 280. Presses 499-499-399. U.P.M.  
When 2 finishers are used finishers get 449 each.  
Two finishers are used when not made over Plug.

In dispute



3400-15 Tall <sup>ftd.</sup> ~~S~~herbet,  
More 750 Presser 3.98 - 358-foot  
finisher 3.23 gatherer 318 U.T.V.



1944 1/2 10 oz Goblet  
move

1944 1/2 8 oz Goblet  
move

1944 5 3/4 Tall Champagne  
move

1944 1/2 1 3/4 oz Wine  
move

1944 1 oz Cordial  
move

1981 11 oz Goblet  
move

1981 9 oz Goblet  
move

1981 6 oz Tall Champagne  
move

1981 Saucer Champagne  
move

1981 1 3/4 oz wine  
move

1981 1 oz Cordial  
move

4071 Ind Almond Footed  
move 825-398-358-323-318 QON

2906 5 1/2 Half Circle  
move 300 448-800p WTW

2900 7 1/2 Half Circle  
move 225 448-800p WTW

2901 Flower Insert 2 1/4" inch Move 725  
Presser 398-358-318.

2901 2 1/2 Flower Insert Move. 700. Presser  
398-358-318

2901 2 7/8 Flower Insert Move. 675-Presser 398  
358-318.

2901 3 1/4 Flower Insert. Move. 650. Presser  
398-358-318.

2900-7" Flower Circle  
Move. 225. W. T. W. Presser 449-Salt 358.

2901 4" Insert  
Move. 525 398-358-318. Q. PAN

2901 5 1/2 Insert  
Move. 450. 438-394-350 Q. PAN



1200 3" Sponge Cup  
 Move. 750-398-358-318.

1200 3 1/2" Sponge Cup  
 Move. 720-398-358-318-

Bottom Panel  
 400. 438-394-350. U.P.C.S.

Budda. Small  
 Move. 250 Transparent Colors. U.T.W.)  
 Move. 256 Non-Transparent Colors. " " "  
 Gather 448 - Gather 358 " " )

1200 1" Figure  
 Move. 448-449-399. U.T.W.

1200 1" Figure  
 Move. 448-449-399. U.T.W.

1200 1" Figure  
 Move. 448-449-399. U.T.W.

1200 5/8" Figure  
 Move. 448-449-399. U.T.W.

1200 1" Figure  
 Move. 448-449-399. U.T.W.

1200 1" Figure  
 Move. 448-449-399. U.T.W.

1200 1" Figure. Move. no Blower 549  
 Gather 448-449-399. U.T.W.